



# Specification Update

## PXA3xx (88AP3xx) Processor Family

### 1. Introduction

This document contains updates to the specifications for the PXA3xx (88AP3xx) Processor Family. This document is a compilation of device and documentation errata, specification clarifications, and specification changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, and tools.

Marvell Corporation has endeavored to include all documented errata in the consolidation process. However, Marvell makes no representations or warranties concerning the completeness of the *PXA3xx Processor Family Specification Update, Rev. 2.0*

Information types defined in [Nomenclature](#) are consolidated into the *PXA3xx Processor Family Specification Update, Rev. 2.0* and are no longer published in other documents.

This document might also contain information that was not previously published.

This document contains the following sections:

- [Section 2. "Affected and Related Documents"](#)
- [Section 3. "Nomenclature"](#)
- [Section 4. "Functional Errata Summary"](#)
- [Section 5. "Detailed Descriptions for Functional Errata"](#)
- [Section 6. "Specification Clarifications Summary"](#)
- [Section 7. "Detailed Descriptions for Specification Clarifications"](#)
- [Section 8. "Specification Changes Summary"](#)
- [Section 9. "Detailed Descriptions for Specification Changes"](#)
- [Section 10. "Documentation Changes Summary"](#)
- [Section 11. "Detailed Descriptions for Documentation Changes"](#)



## 1.1 Document Revision History Table

Table 1: Document Revision History Table

Doc Rev#	Date	Devices Covered	Description of Changes
2.0 (Release C)		PXA32x processor, PXA31x processor and PXA30x processor	Updated Functional Errata: MP-5737,MP-5942, ML-989, MLV-1762, ML-989, MP-5961, MLV-1902, ML-1128, MP-6398, MLV-2026, MP-6346 Removed PXA32x- B1 Functional Errata: MP-5940, MP-6011, MP-5970, MP-6060, MP-6051, MP-6020, MP-5666, MP-5780, MP-5941, MP-5828, MP-5900, MP-6021, MP-6031, MP-6067, MP-6089 Removed PXA31x- A1 Functional Errata :MLV-1762, ML-1069, MLV-1818, MLV-1763, MP-6346 Removed PXA30x- A1 Functional Errata: Removed Specification Changes: ML-1014, MLV-1757 Added Specification Changes: MLV-2213, MLV-1872
2.0 (Release B)	2/06/2009	PXA32x processor, PXA31x processor and PXA30x processor	Added Documentation Changes: MP-6478 Removed Documentation Changes: MLV-2205, MLV-2209, MP-6440, MP-6444, MP-6446, MP-6447, MP-6448, MP-6465, MLV-2238, MLV-2235, MLV-2237, MP-6468, MP-4870, MP-6469, MP-6123, MP-5875 Added Specification Changes: MP-6480
2.0 (Release A)	1/16/2009	PXA32x processor, PXA31x processor and PXA30x processor	Updated Functional Errata: MLV-1902, ML-1128, MLV-2026, MP-6398, MP-6387, MLV-1974, ML-1114 Added Documentation Changes: MP-6478 Updated Documentation Changes: MLV-2205, MLV-2209, MP-6440, MP-6444, MP-6446, MP-6447, MP-6448, MP-6465, MLV-2238, MLV-2235, MLV-2237, MP-6468, MP-4870, MP-6469, MP-6123, MP-5875
2.0		PXA32x processor, PXA31x processor and PXA30x processor	Updated Functional Errata: MLV-1902, ML-1128, MLV-2026, MP-6398, MP-6387, MLV-1974, ML-1114 Added Specification Changes: MLV-1273, MLVM90-13, MLV-2077, MLV-2015, MLV-1960, MLV-2240, MP-6470 Added Documentation Changes: MP-5875 Updated Documentation Changes: MLV-2205, MLV-2209, MP-6440, MP-6444, MP-6446, MP-6447, MP-6448, MP-6465, MLV-2238, MLV-2235, MLV-2237, MP-6468, MP-4870, MP-6469, MP-6123, MP-5875
1.0 (Rev L)	9-30-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Specification Changes: MP-6469, MP-6123
1.0 (Rev K)	09-12-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Specification Changes: MP-6468, MP-4870
1.0 (Rev J)	08-08-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Specification Changes: MP-6465, MLV-2235, MLV-2237, MLV-2237

**Table 1: Document Revision History Table (Continued)**

Doc Rev#	Date	Devices Covered	Description of Changes
1.0 (Rev I)	06-18-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Specification Changes: MLV-2231
1.0 (Rev H)	06-03-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Functional Errata: MP-6451, MLV-2221, ML-1187, ML-1180 Updated Specification Changes: Added Specification Changes:
1.0 (Rev G)	5-02-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Functional Errata: COMP-518 Updated Specification Changes: MP-6444 Added Specification Changes: MP-6446, MP-6447, MP-6448
1.0 (Rev F)	4-18-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Functional Errata: MP-6441 Added Specification Changes: MP-6444
1.0 (Rev E)	4-4-08	PXA32x processor, PXA31x processor and PXA30x processor	Updated Functional Errata: MLV-1902, ML-1128 Added Specification Changes: MLV-2209, MP-6440
1.0 (Rev D)	3-28-08	PXA32x processor, PXA31x processor and PXA30x processor	Removed Specification Changes: MP-6438, MP-6435 Added Specification Changes: MLV-2205
1.0 (Rev C)	3-17-08	PXA32x processor, PXA31x processor and PXA30x processor	Added Functional Errata: MLV-2026, MLV-2166, MLV-2203 Added Specification Changes: MP-6438
1.0 (Rev B)	2-29-08	PXA3xx, Vol. I of the combined Developers Manual	Added item: "The USB 2.0 Device Controller (U2DC) clock enable bit is missing from the D0CKEN_A register descriptions for CKEN6" in <b>Documentation: 6.6 Changes</b> .
1.0 (Rev A)	2-25-08	PXA32x processor, PXA31x processor and PXA30x processor	Initial release of the combined PXA32x processor, PXA31x processor and PXA30x processor.



**Note**

The term "device(s)" is used in this functional errata to refer to the PXA320-B0, PXA320-B1, PXA320-B2, and or any combination of the three. Each erratum has a "Relevant for" section, which specifies to which device(s) the erratum applies.



## 2. Affected and Related Documents

Table 2 lists the documents affected by and related to this errata update. Contact a Marvell representative to obtain the latest revisions of these documents.

**Table 2: Affected Documents / Related Documents**

Title
<i>PXA3xx Processor Family Vol. I: System and Timer Configuration Developers Manual</i>
<i>PXA3xx Processor Family Vol. II: Memory Controller Configuration Developers Manual</i>
<i>PXA3xx Processor Family Vol. III: Graphics and Input Controller Configuration Developers Manual</i>
<i>PXA3xx Processor Family Vol. IV: Serial Controller Configuration Developers Manual</i>
<i>PXA3xx Processor Family Design Guide</i>
<i>PXA3xx Processor Family Processor Electrical, Mechanical, and Thermal Specification (EMTS)</i>
<i>PXA3xx Processors Boot ROM Reference Manual</i>

### 3. Nomenclature

**Errata** are design defects or errors. These errata might cause the PXA3xx (88AP3xx) Processor Family's behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that stepping are present on all devices unless otherwise noted.

**Sightings** are design defects or errors that the root cause has not yet been determined. These are issues that are being seen during early validation that have not been determined to be real bugs or issues with the testers themselves.

**Specification changes and clarifications** describe a modification to the current published specification or further highlight a specification's impact to a complex design situation. These also include any typos, errors, and omissions from the current published specifications. These will be incorporated in any new release of the document.

**Errata BTS#** is an internal database (Jira) that Marvell uses to track and resolve product issues. It is not customer visible. Internal teams are familiar with the Jira numbers listed in this document.



#### Note

Errata in the specification update throughout the product's life cycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata moved from the specification update are archived and made available upon request. Specification changes, specification clarifications, and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (data sheets, manuals, and so forth).



## 4. Functional Errata Summary

The following tables summarize the errata, specification changes, specification clarifications, and documentation changes that apply to the PXA3xx (88AP3xx) Processor Family. These tables use the following notations:

**Table 3: Change Notations**

Notation	Meaning
A0, B0, etc	This errata exists in the PXA3xx (88AP3xx) Processor Family stepping indicated and includes specification change or clarification that applies to this stepping
Plan Fix	This errata will be fixed in a future stepping of the product.
Plan Fix Xx	An attempt to fix this errata was made in stepping Xx
Fixed in Xx	This errata has been fixed in the listed stepping.
No Fix	There are no plans to fix this errata.
Eval	Marvell is still researching this errata.
No Bug	This errata has been determined to be a false errata. Check the workaround section to determine if a document clarification was necessary.
X	This errata exists in the stepping indicated. Specification change or clarification that applies to this stepping
—	This errata is fixed in the listed stepping, or the specification change does not apply to the listed stepping
Shaded	This is either new or has been modified from the previous version of the document

**Table 4: Functional Errata Summary Table**

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.1 Errata (FEr#1)	ROM: Boot ROM reconfigures pads on S2/D3/C4 exit.	page 13	NB	NB	—	—	—
5.2 Errata (FEr#2)	ROM: Unable to exit S2/D3/C4 to DDR when fused for NAND boot.	page 14	NB	NB	—	—	—
5.3 Errata (FEr#3)	ROM: First 32 KB of SRAM is locked when the processor exits Low power modes and resets.	page 14	X	—	—	—	—
5.4 Errata (FEr#4)	ROM: The ICCR[DIM] register gets set when coming out of all resets.	page 15	X	—	—	—	—
5.5 Errata (FEr#5)	ROM: First 1 KB of SRAM is locked when the processor exits Low power mode and resets.	page 15	X	X	X	X	X
5.6 Errata (FEr#6)	ROM: The Boot ROM issues a reset after power on reset that can cause boot failures.		—	—	—	—	—

**Table 4: Functional Errata Summary Table (Continued)**

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.80 Errata (FEr#80)	ROM: Boot ROM clears the OS Timer Count Register 0 (OSCR0) register while handling resets.	page 50	—	—	X	X	X
5.6 Errata (FEr#6)	CORE: L1 cache maintenance operations close to mem ops can overlock the L1 D-cache.	page 15	X	X	X	X	X
5.7 Errata (FEr#7)	CORE: Locking all eight ways in L2 causes the core to hang.	page 16	X	X	—	—	—
5.8 Errata (FEr#8)	CORE: Debug - hold reset cannot be set before reset is asserted.	page 17	X	X	X	X	X
5.9 Errata (FEr#9)	CORE: A rejected request is retried out of order at the core interface.	page 17	X	X	—	—	—
5.10 Errata (FEr#10)	CORE: dbg txrxctl rr bit gets set when it should not.	page 18	X	X	X	X	X
5.11 Errata (FEr#11)	CORE: Aborted PLD sets lock bit.	page 18	X	X	X	X	X
5.12 Errata (FEr#12)	CORE: In Special Debug State, data can return twice to a register for an aborting load.	page 21	X	X	X	X	X
5.18 Errata (FEr#18)	CORE: Possible instruction corruption during page table Read.		—	—	—	—	—
5.19 Errata (FEr#19)	CORE: Possible Page table corruption during Read.		—	—	—	—	—
5.13 Errata (FEr#13)	Core: Data Cache Unit (DCU1) hangs in an infinite recirculate loop which results in data not being returned to the register file.	page 22	X	X	—	—	X
5.14 Errata (FEr#14)	Core: Data Cache Unit (DCU2) Hang with Strongly Ordered Memory	page 23	X	X	—	—	—
5.15 Errata (FEr#15)	Core: System hangs occur while changing operating points when two back to back reads from internal SRAM, the Static Memory Controller, the Dynamic Memory Controller, System Bus 1/System Bus 2 or between the system buses occur.	page 24	X	—	X	—	X
5.76 Errata (FEr#76)	CORE: Random system hangs may occur when exiting S0/D0CS/C1	page 48	X	—	X	—	X
5.16 Errata (FEr#16)	PIN CONTROL: Glitches can occur when entering low power mode (S0/D1/C2, S0/D2/C2 and S2/D3/C4)	page 24	X	X	—	—	X
5.17 Errata (FEr#17)	PIN CONTROL: Signals can glitch while entering a hardware or GPIO reset	page 25	X	X	—	—	—
5.18 Errata (FEr#18)	PIN CONTROL: Signals can glitch when a BATT_FAULT occurs.	page 25	X	X	X	X	X
5.19 Errata (FEr#19)	CLK: Ring oscillator frequency may go out of spec leading to UART failures.	page 25	X	X	—	—	X
5.20 Errata (FEr#20)	PMU: When leaving S3/D4/C4, command to reset the voltages not sent to PMIC.	page 25	X	X	X	X	X



Table 4: Functional Errata Summary Table (Continued)

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.21 Errata (FEr#21)	PMU: When ACCR[PCCE] = 1 the AGENP[RO_ST] (MP-6377) may not reflect the correct status of the 120 MHz right oscillator.	page 26	X	X	X	X	X
5.22 Errata (FEr#22)	APMU: System hangs may occur when three separate operations execute between the Application Subsystem Power Management Unit (APMU), Application Subsystem Clock Control Unit (ACCU) OS Timers (OST), and Intel XScale® core.	page 26	X	X	X	X	X
5.23 Errata (FEr#23)	APMU: Any Writes to the Application Subsystem Interrupt Control/Status Register (AICSR) register clear the interrupt status bits.	page 30	X	X	X	X	X
5.24 Errata (FEr#24)	SERVICES: GPIO reset wakes up the processor from S3/D4/C4.	page 30	X	X	X	X	X
5.25 Errata (FEr#25)	SERVICES: Unexpected PWR_I2C commands sent on ACCR write.	page 30	X	X	X	X	X
5.26 Errata (FEr#26)	SERVICES: Two sets of PWR I2C sent on S2 exit.	page 30	X	X	X	X	X
5.49 Errata (FEr#49)	SERVICES: 13 MHz stability counter too small (similar to start-of-day problem).		—	—	—	—	—
5.27 Errata (FEr#27)	SERVICES: nRESET_IN ignored during start-of-day when VCC_BBATT is less than 2.4V.	page 31	X	X	X	X	X
5.52 Errata (FEr#52)	SERVICES: BATT_FAULT status bit not set between SYS_EN and PWR_EN on a hardware reset.		—	—	—	—	—
5.28 Errata (FEr#28)	SERVICES: SRAM is not retained during a GPIO RESET, and the Boot ROM resumes to SRAM in Non-debug mode.	page 31	X	X	—	—	—
5.29 Errata (FEr#29)	SERVICES: Lockup occurs if nBATT_FAULT asserted after sys_Del count is done and the battery does not have enough energy to complete Start-of-Day sequence.	page 31	X	X	—	—	—
5.30 Errata (FEr#30)	SERVICES: System hangs may occur when increasing operating points from 208 MHz or 416 MHz, or when using 806 MHz or 416 MHz Idle modes.	page 32	X	—	X	—	X
5.82 Errata (FEr#82)	SERVICES: EXT_WAKEUP<1:0> wakes up on both rising and falling edges regardless of PWER[WEX[1:0]] settings.	page 51	X	X	X	X	X
5.31 Errata (FEr#31)	1-WIRE: Reads bad data when Receive-Buffer-Full status bit is set.	page 33	X	X	X	X	X
5.32 Errata (FEr#32)	1-WIRE: PD flag not cleared when read (when interrupts are disabled).	page 34	X	X	X	X	X
5.33 Errata (FEr#33)	INTERRUPT CONTROLLER: Unexpected exception vector when ICCR[DIM]=0 and ICMR=0.	page 34	X	X	X	X	X



**Table 4: Functional Errata Summary Table (Continued)**

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.34 Errata (FEr#34)	RTC: Wristwatch alarm does not interrupt at the correct time of day	page 35	X	X	X	X	X
5.35 Errata (FEr#35)	OST: Extra count after match when the Match Control registers are set.	page 35	X	X	X	X	X
5.81 Errata (FEr#81)	OS Timer interrupts 4 – 11 are missed when an OS Timer Status Register (OSSR) Write occurs at the same time as a match-event interrupt occurs.	page 50	X	X	X	X	X
5.36 Errata (FEr#36)	DMC: Writes to uninitialized memory can hang the system.	page 35	X	X	X	X	X
5.64 Errata (FEr#64)	DMC: DDR not always functional after S2/D3/C4 exit with Early Start (use ring oscillator) enabled, or when entering/exiting S2/D3/C4 while in S0/D0CS/C0		—	—	—	—	—
5.65 Errata (FEr#65)	DMC: DDR Write transactions hanging at 104 MHz due to switch not completing transaction.		—	—	—	—	—
5.37 Errata (FEr#37)	DMC: DDR failures occur at VCC_APPS <= 975 mV.	page 36	—	—	—	—	X
5.38 Errata (FEr#38)	SMC: When using DMA and the ALT bit in the Address Configuration Registers (CSADRCFGx) is set to 0b00 or 0b01 corruption occurs on the bus.	page 36	X	X	—	—	—
5.39 Errata (FEr#39)	SMC: Last LUA of PCMCIA transaction always has the ALW bit in the Address Configuration Registers (CSADRCFGx) set to 1.	page 36	X	X	—	—	—
5.40 Errata (FEr#40)	SMC: If MECR[CIT] is 0, a Read/Write to the PC card memory space hangs.	page 37	X	X	—	—	—
6.12 Errata (FEr#12)	NFC: Incorrect interrupts reported when running in DMA mode.		—	—	—	—	—
5.41 Errata (FEr#41)	NFC: Sequential row Reads do not read data correctly with 16-bit NAND.	page 37	—	—	—	—	X
5.42 Errata (FEr#42)	NFC: NAND timing sensitivity on the clocks feeding the NFC registers.	page 37	—	—	X	X	X
5.51 Errata (FEr#51)	NFC: NAND Read data corruption at lower product points (104 MHz and 208 MHz).		—	—	—	—	—
5.43 Errata (FEr#43)	MMC/SD/SDIO: CS de-assertion/re-assertion timing.	page 38	X	X	X	X	X
5.44 Errata (FEr#44)	MMC/SD/SDIO: MMC does not detect CRC errors or missing stop bit.	page 38	X	X	X	X	X
5.45 Errata (FEr#45)	MMC: MMC_CLK glitch in S0/D0CS/C0.	page 39	X	X	—	—	—
5.46 Errata (FEr#46)	LCD: Data not correct from Overlay 2 in YCbCr 4:2:0 mode.	page 39	X	X	X	X	X



Table 4: Functional Errata Summary Table (Continued)

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.47 Errata (FEr#47)	LCD artifacts occur when exiting S0/D1/C2.	page 39	—	—	X	X	X
5.48 Errata (FEr#48)	LCD: VGA screens not supported when using S0/D1/C2 mode.	page 40	—	—	X	X	X
5.49 Errata (FEr#49)	LCD: Insufficient bandwidth to support 640x480 screens when using DDR for the Frame buffer in S0/D0CS/C0 mode.	page 40	X	—	—	—	X
5.50 Errata (FEr#50)	LCD: The MSB acts as both the T-bit and red color when using RGB565 with Chroma Keying enabled on Overlay 1 and Overlay 2.	page 40	—	—	X	X	—
5.77 Errata (FEr#77)	LCD: VGA Input and Output FIFO under-runs can occur while running in S0/D0CS/C0.	page 49	—	—	X	X	—
5.51 Errata (FEr#51)	CI: CGC LUT load gets corrupted due to READ/WRITE pointer collision.	page 40	X	X	X	X	X
5.52 Errata (FEr#52)	CI: Camera FIFO overflow when slow memory accesses occur.	page 41	X	X	X	X	X
5.53 Errata (FEr#53)	CI: Scaling unit computes bad values for Y value of YCrCb scaling.	page 41	X	X	—	—	—
5.78 Errata (FEr#78)	CI: QCI will capture one line of invalid data	page 49	X	X	X	X	X
5.54 Errata (FEr#54)	GCU: STR_BLT instruction hangs when Source and Destination buffers are in external SRAM, does not return correct data occasionally when buffers are in DDR.	page 41	X	X	—	—	X
5.55 Errata (FEr#55)	GCU: Pattern copy fails for random test cases with data mismatch.	page 42	X	X	X	X	X
5.56 Errata (FEr#56)	KEYPAD: Wrong clock divider in S0/D0CS/C0 mode is causing keypad detection problems.	page 42	X	X	—	—	—
5.57 Errata (FEr#57)	TSI: TSI controller takes almost 2 ms to start up after exiting Low-power mode.	page 42	X	X	—	—	—
5.58 Errata (FEr#58)	TSI: Discontinuity in A/D conversions near 64-count boundaries in 12-bit mode.	page 42	X	X	—	—	—
5.59 Errata (FEr#59)	TSI exhibits differing conversion times.	page 43	X	X	—	—	—
5.60 Errata (FEr#60)	TSI: Steady state conversion variability > 4 counts.	page 43	X	X	—	—	—
5.61 Errata (FEr#61)	TSI: ADCS[RUN] not cleared by TSI state machine	page 43	X	X	—	—	—
5.62 Errata (FEr#62)	TSI: Stylus-up interrupt not reliably generated when XY=1, CC=0, also generating extra Stylus down/up interrupts in continuous conversion (XY=1, CC=1).	page 43	X	X	—	—	—
5.63 Errata (FEr#63)	UDC: FIFO content of an IN endpoint not flushed by FEF when double-buffered	page 45	X	X	—	—	X

**Table 4: Functional Errata Summary Table (Continued)**

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.64 Errata (FEr#64)	U2DC: Corrupted EOP in Full-speed mode causes the U2D to hang.	page 45	X	X	—	—	X
5.65 Errata (FEr#65)	U2DC: DMA Control/Status register reports “end of Receive” interrupt on “IN” endpoints	page 45	X	X	—	—	X
6.47 Errata (FEr#47)	U2DC: DMA not writing data correctly to FIFO when source address is not 8-byte aligned.		—	—	—	—	—
6.48 Errata (FEr#48)	U2DC: Stopping DMA when SP interrupt occurs causes DMA status error.		—	—	—	—	—
5.66 Errata (FEr#66)	U2DC: Internal USB host/client resistors may be out of spec above 40 degrees C.	page 45	X	X	—	—	—
6.50 Errata (FEr#50)	U2DC: IN endpoint sends incorrect data and causes a NAK on OUT transfers, if the DMA is started for the next transfer before the FIFO is empty.		—	—	—	—	—
6.51 Errata (FEr#51)	U2DC: Endpoints with default alternate setting in non-zero interface send STALL after SET CONFIGURATION.		—	—	—	—	—
6.52 Errata (FEr#52)	U2DC: Signals between U2D and the system bus can be missed at a bus clock frequency of 104 MHz.		—	—	—	—	—
6.53 Errata (FEr#53)	U2DC: Stall on PING token packets (bulk out or EP0 out) may have incorrect response.		—	—	—	—	—
6.54 Errata (FEr#54)	U2DC: Setting FST does not STALL an endpoint not affected by an active SET_INTERFACE		—	—	—	—	—
6.55 Errata (FEr#55)	U2DC: STALL response when an incoming host request collides with an Endpoint FIFO flush.		—	—	—	—	—
5.69 Errata (FEr#69)	ULPI_STP asserts upon exiting S0/D1/C2 and S0/D2/C2 modes.		—	—	—	—	—
5.67 Errata (FEr#67)	USBH: USB host Port 3 in Transceiverless mode may not work correctly with an external device.	page 46	X	X	—	—	X
5.68 Errata (FEr#68)	USBH: USB host fails with system bus = 104 MHz or 208 MHz.	page 46	—	—	—	—	X
5.69 Errata (FEr#69)	SSP: EOR is not set when FIFO Packed mode is used.	page 46	X	X	X	X	X
5.70 Errata (FEr#70)	SSP: SSP not functional when entering and exiting S0/D0CS/C0 prior to enabling SSP.	page 47	X	X	—	—	—
5.71 Errata (FEr#71)	UART: When DLL and DLH are programmed at the same time, UART takes in only the first one.	page 47	X	X	X	X	X
5.72 Errata (FEr#72)	UART: TX interrupt can be missed when running full duplex	page 47	X	X	—	—	X



Table 4: Functional Errata Summary Table (Continued)

Erratum Number	Erratum Description	Page	PXA32x - B2	PXA32x - C0	PXA31x - A2	PXA31x - B1	PXA30x-A1.A
5.73 Errata (FEr#73)	CIR: Wrong symbols sent on second transmission after boot.	page 48	X	X	X	X	X
5.74 Errata (FEr#74)	I2C: Bus Busy bit only changes on state transitions.	page 48	X	X	X	X	X
5.75 Errata (FEr#75)	I2C: Enabling I2C unit drives SCL low.	page 48	X	X	—	—	—
5.79 Errata (FEr#79)	The I2C Unit Not Busy bit (ISR[UB]) remains set after Master Abort	page 50	X	X	X	X	X

## 5. Detailed Descriptions for Functional Errata

Refer to [Section Table 4: "Functional Errata Summary Table" on page 6](#) to determine which errata are new to this report.

### 5.1 Errata (FEr#1)

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Bug

**Errata BTS#:** MP-5737

**Description:** ROM: Boot ROM reconfigures pads on S2/D3/C4 exit.

**Problem:** The Boot ROM reconfigures MFPRs on S2/D3/C4 exit. These registers should not be modified by the Boot ROM.

**Implication:** For a Resume on a non-trusted NAND platform, the Resume address is taken from the PSPR register and Resume transfers to ISRAM and no MFPR pads are set. Refer to [Table 5](#) for Multi-Function Pin Register (MFPR) Boot ROM configurations. Procedures required for exiting S2/D3/C4 are documented in the *PXA3xx Processors Boot ROM Reference Manual*.

**Table 5: Multi-Function Register Pin (MFPR) Settings**

Ball Name	Address	Value
GPIO2	0x40E1_012C	0x0000_0001
GPIO3	0x40E1_0134	0x0000_0001
GPIO4	0x40E1_0134	0x0000_0001
nXCVREN	0x40E1_0138	0x0000_1900
nBE0	0x40E1_0214	0x0000_1800
nBE1	0x40E1_0218	0x0000_1800
nLUA	0x40E1_0234	0x0000_1900
nLLA	0x40E1_0238	0x0000_1900
DF_ADDR0	0x40E1_023C	0x0000_1800
DF_ADDR1	0x40E1_0240	0x0000_1800
DF_ADDR2	0x40E1_0244	0x0000_1800
DF_ADDR3	0x40E1_0248	0x0000_1800
DF_CLE	0x40E1_0204	0x0000_1800
DF_ALE_NWE1	0x40E1_0208	0x0000_1801
DF_IO0	0x40E1_024C	0x0000_1401
DF_IO1	0x40E1_0254	0x0000_1401
DF_IO2	0x40E1_025C	0x0000_1401
DF_IO3	0x40E1_0264	0x0000_1401
DF_IO4	0x40E1_026C	0x0000_1401
DF_IO5	0x40E1_0274	0x0000_1401



Table 5: Multi-Function Register Pin (MFPR) Settings (Continued)

Ball Name	Address	Value
DF_IO6	0x40E1_027C	0x0000_1401
DF_IO7	0x40E1_0284	0x0000_1401
DF_IO8	0x40E1_0250	0x0000_1401
DF_IO9	0x40E1_0258	0x0000_1401
DF_IO10	0x40E1_0260	0x0000_1401
DF_IO11	0x40E1_0268	0x0000_1401
DF_IO12	0x40E1_0270	0x0000_1401
DF_IO13	0x40E1_0278	0x0000_1401
DF_IO14	0x40E1_0280	0x0000_1401
DF_IO15	0x40E1_0288	0x0000_1401

**Workaround:** The MFPRs must be reconfigured by software after S2/D3/C4 exit.

### 5.2 Errata (FEr#2)

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Bug

**Errata BTS#:** MP-5942

**Description:** ROM: Unable to exit S2/D3/C4 to DDR when fused for NAND boot.

**Problem:** When fused for NAND boot, it is not possible to exit S2/D3/C4 and boot to DDR.

**Implication:** Cannot directly go from S2/D3/C4 to DDR execution.

**Workaround:** The Boot ROM does not currently support direct exit from S2/D3/C4 to DDR. The first bank of SRAM must be kept on while in S2/D3/C4. The procedures for exiting S2/D3/C4 are documented in the *PXA3xx Processors Boot ROM Reference Manual* and do not include resuming from DDR.

### 5.3 Errata (FEr#3)

**Type:** Functional Errata

**Relevant for:** PXA32x - B2

**Fixed in:** PXA32x - C0

**Errata BTS#:** ML-989

**Description:** ROM: First 32 KB of SRAM is locked when the processor exits Low power modes and resets.

**Problem:** In non-trusted boot, the Wireless Trusted Module (WTM) locks the first 32 KB of internal SRAM.

**Implication:** Software requiring access to this 32 KB of SRAM is unable to do so.

**Workaround:**

Software Workaround

Coming out of hardware/GPIO/watchdog reset or S3/D4/C4 mode:

1. Set the CTMCR[0] (0x4300\_0010) bit after BOOTROM hands control to OBM.
2. Disable the WTM clock by clearing D0CKEN\_A[CKEN[19]] register.

Going into S2/D3/C4:

1. Enable WTM clock by setting the D0CKEN\_A[CKEN[19]] register.
2. Enable Mini-LCD clocks by setting DOCKEN\_B[CKEN[17]] register if it is not enabled.

Coming out of S2/D3/C4:

1. D0CKEN\_A[CKEN[19]] and D0CKEN\_B[CKEN[17]] can be disabled to save power.
- 

#### 5.4 Errata (FEr#4)

**Type:** Functional Errata

**Relevant for:** PXA32x - B2

**Fixed in:** PXA32x - C0

**Errata BTS#:** MLV-1762

**Description:** ROM: The ICCR[DIM] register gets set when coming out of all resets.

**Problem:** Coming out of all resets, the Boot ROM sets the ICCR[DIM] register.

**Implication:** By setting the ICCR[DIM] register only active, unmasked interrupts as defined in the ICMR register bring the processor out of S0/D0/C1 modes. This bit is ignored in the S0/D0/C0 run mode.

**Workaround:** Software must clear this register after a reset to detect wakeups from the sources defined in the ICPR registers when running in S0/D0/C1 mode.

---

#### 5.5 Errata (FEr#5)

**Type:** Functional Errata

**Relevant for:** PXA30x-All, PXA31x-All, PXA320-All

**Fixed in:** No Fix

**Errata BTS#:** ML-989

**Description:** ROM: First 1 KB of SRAM is locked when the processor exits Low power mode and resets.

**Problem:** In Non-Trusted boot, the Wireless Trusted Module (WTM) locks the first 1 KB of internal SRAM.

**Implication:** Software requiring access to this 1 KB of SRAM is unable to access it.

**Workaround:**

Software Workaround

Coming out of hardware/GPIO/watchdog reset or S3/D4/C4 mode:

1. Set the CTMCR[0] (0x4300\_0010) bit after BOOTROM hands control to OBM.
2. Disable the WTM clock by clearing D0CKEN\_A[CKEN[19]] register.

Going into S2/D3/C4:

1. Enable WTM clock by setting the D0CKEN\_A[CKEN[19]] register.
2. Enable Mini-LCD clocks by setting DOCKEN\_B[CKEN[17]] register if it is not enabled.

Coming out of S2/D3/C4:

1. D0CKEN\_A[CKEN[19]] and D0CKEN\_B[CKEN[17]] can be disabled to save power.
- 

#### 5.6 Errata (FEr#6)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x-All

**Fixed in:** No Fix

**Errata BTS#:** Core ARS 3584

**Description:** CORE: L1 cache maintenance operations close to mem ops can overlock the L1 D-cache.

**Problem:** Results in locations being locked into the L1 data cache incorrectly.

---



Memory operations when the L1 data cache is set up for locking (Bit 0 of the L1 Data Cache Lock register is set) can set the lock bit for a different line as well as the preferred line, within the same set. This occurs when the memory operation stalls in the data-cache pipeline due to a L1 cache maintenance instruction preceding the memory operation.

This bug is similar to errata #3544. This affects locking into the L1 data cache only. Locking the L1 instruction cache or the L2 cache are not affected. This bug can occur only during the process of locking data into the L1 data cache. Once the data cache has been locked down, the bug has no impact.

Steps that expose the bug:

1. Enable DCU locking
2. Perform an L1 cache maintenance operation (defined in subsequent paragraphs)
3. Perform a memory operation followed immediately by a cache-maintenance operation. This sequence is stalled in the third data-cache stage of the pipe by the cache-maintenance operation.

A full list of affected L1 cache maintenance commands follows:

mcr p15, 0, Rd, c7, c6, 1 - Invalidate L1 D-cache by MVA  
mcr p15, 0, Rd, c7, c10, 1 - Clean L1 D-cache by MVA  
mcr p15, 0, Rd, c7, c10, 2 - Clean L1 D-cache by set/way  
mcr p15, 0, Rd, c7, c14, 1 - Clean and invalidate L1 D-cache by MVA  
mcr p15, 0, Rd, c7, c14, 2 - Clean and invalidate L1 D-cache by set/way

**Implication:** A location in the same set of the L1 data cache as the stalled memory operation in Step 3 above may be locked and not available for allocation. Data is not modified or corrupted.

**Workaround:** Two workarounds exist:

**Workaround #1:** Do not perform L1 cache-control commands while in DCU locking mode.

**Workaround #2:** Possible: Separate L1 cache-control commands by at least a single non-memory operation instruction while in DCU locking mode to avoid the stall condition.

---

## 5.7 Errata (FEr#7)

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** Core ARS 3251

**Description:** CORE: Locking all eight ways in L2 causes the core to hang.

**Problem:** The replacement behavior on a miss in the L2 cache on a line where all eight ways have been locked is defined as “architecturally unpredictable.” However, the implementation treats “all ways locked” as “no ways locked”, and as such, normal replacement schemes (excluding lock behavior) dictate which line gets replaced.

A corner case is associated with this condition. Normally, when all ways are locked in the L2, the lock bits would be ignored and find the first way that is “not used and not pend” for selecting a replacement. However, in certain situations, there is no way left that is “not used and not pend”. The result is that the



default replacement is used, and a way that is marked PEND is replaced erroneously.  
**Implication:** Locking all eight ways in L2 causes the core to hang.  
**Workaround:** Do not lock all eight ways.

---

#### 5.8 Errata (FEr#8)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** Core ARS 3401

**Description:** CORE: Debug - hold reset cannot be set before reset is asserted.

**Problem:** The hold\_reset bit (accessed through JTAG in DCSR data reg) is what the debugger uses to hold the core in reset while the debugger downloads the debug handler into the SRAM. Typically, a user would set this bit during reset assertion to the chip (and core). Prior to the PXA3xx (88AP3xx) Processor Family core, the debugger could also set this bit even when the core was not in reset, but it would not have any effect until the next core reset. The core would stay in reset until the debugger cleared the keep\_reset bit.

On the PXA3xx (88AP3xx) Processor Family core, setting this bit prior to reset results in unpredictable behavior when the core comes out of reset. The problem is that while this bit is set, some internal core states are not reset. So, setting this bit during reset (specifically, after the core enters reset) works because there is a point when the core is in reset, but keep\_reset has yet to be set by the debugger. Setting this bit prior to reset means when the reset occurs, there is no time at which reset is asserted without keep\_reset also being asserted. So this latter case results in some core states not being reset. After reset, this process results in unpredictable operation of the core.

This feature is not commonly used, and with the addition of hot-debug hardware to the core, the new hot-debug capabilities provide an alternative solution. Also, since vendors will be using the new hot-debug features (regardless of this keep\_reset issue), there is no significant impact on the tools.

**Implication:** PXA3xx (88AP3xx) Processor Family core debug features are not compatible with the PXA27x core.

**Workaround:** The debugger must set the keep\_reset bit only after the core has already entered reset. Setting this bit while the core is not already in reset results in unpredictable core behavior.

---

#### 5.9 Errata (FEr#9)

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** Core ARS 3501

**Description:** CORE: A rejected request is retried out of order at the core interface.

**Problem:** If all the conditions below occur, the L1 data cache clean command may proceed when there are no available buffers. Whether it hits or misses, it corrupts a buffer, which can lead to unpredictable behavior.

Steps that expose the bug:

1. The following code sequence (back to back, with no intervening instructions):
    - a) Any memory operation (Load, Store, Cache Management operation, etc.)
    - b) L2 cache control command (Clean, Invalidate, etc.)
    - c) L1 data cache clean command (by MVA or by set/way)
  2. The Memory buffers are full (heavy recent load/store traffic).
  3. Two memory transactions complete within 1-2 cycles freeing up their buffers.
-



This situation can occur even if all pages are marked as writethrough. The Clean command does not have to hit the cache or hit dirty data for the bug to occur.

- Implication:** Possible symptoms:
- Dropped memory transaction (load or store)
  - Part hangs
  - Incorrect data stored out
  - Incorrect data returned to a register

**Workaround:** Separate L1 and L2 cache control commands by at least a single non-cache control instruction.

---

#### 5.10 Errata (FEr#10)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** Core ARS 3551

**Description:** CORE: dbg txrxctl rr bit gets set when it should not.

**Problem:** This bug occurs when the RX register has a new valid value loaded into it and the rx\_valid bit is then polled by the external debugger to determine if the core has read the value. There is a window (approximately six TCK cycles) between the update-DR in the JTAG polling loop of the rx\_valid bit and the reading of the RX register by the core software. The read of the RX register by the core clears the TXRXCTL[RR] flag but the polling of the rx\_valid bit via JTAG in this window can set the TXRXCTL[RR] flag erroneously again.

**Implication:** When software running on the core communicates to an external debugger, the TXRXCTL[RR] flag can be set erroneously even when there has not been a new DBGRX update sent in via JTAG. In other words, the core software can “think” it has received a new RX data value when, in fact, the debugger did not send a new value.

**Workaround:** Two workarounds exist:

**Workaround #1:** Use the debug handler recommended by Marvell.

**Workaround #2:** A software workaround for custom debug-handler software is as follows:

- Modify the core software so that after the core reads the RX register, it transmits an “acknowledgement” message containing some recognizable data value to the debugger via the DBGTX register signaling that it has read the RX register.
  - The debugger should have a corresponding modification so that it does not poll the DBGRX register again (after sending a valid message) until it “sees” the core software acknowledgement message. Once it detects the acknowledgement message, it can either poll DBGRX or send another message.
- 

#### 5.11 Errata (FEr#11)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, LV-all  
**Fixed in:** No Fix  
**Errata BTS#:** Core ARS 3558

**Description:** CORE: Aborted PLD sets lock bit.

**Problem:** This issue results in locations being locked in the cache incorrectly. If a PLD instruction that does not have permission to access a given memory region is used during data-cache locking, then the DCU may incorrectly lock a “hole” into the data cache, effectively reducing the data cache size by one line.

---

PLD instructions are defined to NOT abort – that is, if they do not have permission to access a line from memory; they are supposed to turn into a NOP: the data cache should not be updated. In this bug, the data cache is updated with a locked invalid line.

Steps that expose the bug:

1. Enable L1 data-cache locking.
2. Perform a PLD instruction that does not have permission.

**Implication:** This process affects locking into the L1 data cache only. Locking the L1 instruction cache or the L2 cache are not affected.

This bug can occur only during the process of locking data into the L1 data cache. Once the data cache has been locked down, the bug has no impact.

Data aborts taken while the lock bit is set are dangerous because memory operations executed in the abort handler will be locked.

**Workaround:** Use the L1 locking routine specified below or in the PXA3xx (88AP3xx) Processor Family Software Developers Guide:

```
@ Restrictions:
@
@ Prefetch abort handler MUST turn off lock mode bit
@ as soon as possible.
@
@ Data abort handler MUST turn off lock mode bit as
@ soon as possible.
@
@ If there are any imprecise aborts during locking
@ the result of locking is unpredictable.
@
@ PSR bit defines
.setPSR_I, 0x80
.setPSR_F, 0x40
@ LockDCache flags
.setL_LEN, 0x01
.setL_INV, 0x02
@ Data Cache Lock Mode
.setM_LOCKED, 0x01
.setM_NOT_LOCKED, 0x00
@ Cache Line Size
.setLINE_SIZE, 0x20
@
@ _LockDCache(Start,End_or_Length,Flags)
@
@ Inputs
@ R0 Start Address
@ R1 End Address (inclusive) or Length
```



```
@ R2 Flags
@
@ Outputs
@ R0 Success (1) / Failure (0)
@
@ Registers used
@ R1 - R3, IP
@
@ Usage:
@
@ If a region length is specified in R1 then the
@ L_LEN flag must be set. All data cache will be
@ unlocked and invalidated if the L_INV flag is set.
@ If several things are to be locked into the cache
@ the L_INV flag should be set for the first item
@ to be locked and clear for subsequent items.
@
.align 2
.global _LockDCache
.type _LockDCache,function
_LockDCache:
mrs ip, cpsr @ Save CPSR
orr r3, ip, #PSR_I | PSR_F
msr cpsr_c, r3 @ Disable Interrupts
mrc p15, 0, r3, 1, 0, 0
mcr p15, 0, r3, 1, 0, 0 @ Force a DCU drain
tst r2, #L_INV
mcrne p15, 0, r0, c9, c6, 1 @ Unlock D-Cache
mcrne p15, 0, r0, c7, c6, 0 @ Invalidate D-Cache
mov r3, #M_LOCKED
mcr p15, 0, r3, c9, c6, 0 @ Set Lock Mode
tst r2, #L_LEN
addne r1, r1, r0
cmpne r1, r0
subne r1, r1, #1
CacheFill:
@ Uncomment the DCU drain code for REV A0 silicon
ldr r2, [r0], #LINE_SIZE
@ mrc p15, 0, r3, 1, 0, 0
@ mcr p15, 0, r3, 1, 0, 0 @ Force a DCU drain
cmp r0, r1
ldr!s r3, [r0], #LINE_SIZE
@ mrcls p15, 0, r3, 1, 0, 0
@ mcrls p15, 0, r3, 1, 0, 0 @ Force a DCU drain
```

```
cmp1s r0, r1
bls CacheFill
orr r2, r2, r3 @ Create a dependency stall
mrc p15, 0, r0, c9, c6, 0 @ Read Lock Mode
mov r2, #M_NOT_LOCKED
mcr p15, 0, r2, c9, c6, 0 @ Clear Lock Mode
msr cpsr_f, ip @ Reset Interrupt flags
and r0, r0, #M_LOCKED @ Test lock flag
mov pc, lr
.Lfe1:
.size _LockDCache, .Lfe1-_LockDCache
```

---

### 5.12 Errata (FEr#12)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** Core ARS 3497

**Description:** CORE: In Special Debug State, data can return twice to a register for an aborting load.

**Problem:** This situation results in the DCU returning twice to a register for an aborting load in SDS (Special Debug State).

In SDS, memory operations that would normally abort and cause an event flush do not. Instead, they are supposed to cease operation; specifically, clear the scoreboard bit, and set the “sticky” abort bit in the DCSR. For certain aborting loads, the DCU detects that the load is programmed to abort and clear the scoreboard bit, but also sends out a memory request for the aborting load – additionally, the DCU then returns the incorrect data to the register file.

Steps that expose the bug:

1. An outstanding store in one of the DCU memory buffers has not been globally observed.
2. A strongly ordered operation is executed (either a load or a store).
3. Before the strongly ordered operation in (2) has been globally observed, a Load operation that aborts is executed. Because of (1) and (2), the DCU incorrectly returns twice to the register file.

**Implication:** Special Debug State does not operate correctly.

**Workaround:** A software workaround is appropriate since this bug occurs only during SDS.

Two workarounds exist:

**Workaround #1:** Before executing any load that “could” data abort, perform a DCU DRAIN\_WRITEBUFFER (dwb) command (defined below).

**Workaround #2:** Because any load in SDS may abort and return incorrect data to a register, check the “sticky” abort bit in the DCSR before using the data from the load in question. This bug does not occur if a DCU\_DRAIN (defined below) command is executed before any of the data from the loads is used. Additionally, performing a DCU\_DRAIN command before reading the “sticky” abort bit in the DCSR has the added benefit that any imprecise data aborts on the loads have set the abort bit before the data is used.

1. Perform any number of Loads/Stores.
2. Perform the following before the data from the Loads is used:
  - a) DCU\_DRAIN

- b) Read the “sticky” abort bit and verify that no aborts have occurred
- c) Use the data from the Loads

DCU\_DRAIN is defined as:

mrc p15, 0, r3, c1, c0, 0 @# read CP15 Control register

mcr p15, 0, r3, c1, c0, 0 @# write CP15 Control register

[the mcr stalls until the L1 D cache buffers have completely drained]

DCU\_DRAIN\_WRITEBUFFER is defined as:

mcr p15, 0, r0, c7, c10, 4 @# drain write buffer (dwb)

### 5.13 Errata (FEr#13)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6244, ML-981, MLV-1723

**Description:** Core: Data Cache Unit (DCU1) hangs in an infinite recirculate loop which results in data not being returned to the register file.

**Problem:** With the L1 Data Cache cacheable -or- L1 Data Cache uncacheable and the L2 Cache cacheable, a specific sequence of loads and stores to the Data Cache Unit and a specific sequence of data being returned within an extremely narrow timing window can cause the Data Cache Unit to hang in an infinite loop.

Required conditions for replicating the issue with and without evictions (All Loads/Stores are to L1 cacheable memory -or- L1 uncacheable and L2 cacheable memory):

1. A Load misses the L1 data cache and must cause an eviction of a clean cacheline in the same set. However, this first load is not necessary (which means the L1D eviction is not a necessary condition).
2. A store is being retried by the Data Cache Unit due to a backed up Bus Interface Unit.
3. Four loads to the same cacheline that miss the data cache.
4. The following timing conditions must then happen:
  - Must have some other unrelated instructions with no register dependencies occurring between #3 and #5.
5. A load, which is to the same cacheline as the store in #2, misses the data cache.
  - The first Load in #3 gets its data back into the Data Cache Unit exactly one cycle after this load gets executed.
  - The Store in #2 still retries from the Data Cache Unit and one of the attempts happens exactly one cycle after this load gets executed.
  - No dependencies on previous loads.
6. A Load, which is to the same cacheline as the four loads in #3, misses the data cache.
  - No dependencies on previous loads.
  - Must be back-to-back with #5.
7. A Load operation to any address.
  - Must be back-to-back with #6.

**Implication:** If the Data Cache Unit encounters this condition, it enters an infinite loop, resulting in no data being returned and thereby, hanging the processor core.

Notes:

- This issue has been observed only on an SOC not related to the PXA3xx processors while running hand-tuned focus tests written to specifically reproduce this issue.
- The only way to exit this condition is to reset the XScale® core.
- Independent of L1 data cache operating in Writethrough or Writeback mode.
- Independent of whether L2 cache is present.
- Independent of Bus timings/ratios.

**Workaround:** No workaround. However, there is a recovery mechanism in the unlikely event that it does occur. If a lockup does occur, the only way to exit this condition is to reset the processor core. Examining the trace buffer after a reset provides information on the code sequencing (within 16 clock cycles) leading to the lockup. Once identified, code corrections can be made to eliminate the condition as listed in the "Required Conditions" section above that created the lockup.

---

**5.14 Errata (FEr#14)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6251, ML-983, MLV-1726

**Description:** Core: Data Cache Unit (DCU2) Hang with Strongly Ordered Memory

**Problem:** With the L1 Data Cache cacheable -or- L1 Data Cache uncacheable and the L2 Cache cacheable, a specific sequence of loads and stores to the Data Cache Unit with a strongly ordered load and a specific sequence of data being returned within an extremely narrow timing window can cause the Data Cache Unit to hang, thereby hanging the processor core.

Required Conditions (All Loads/Stores are to L1 cacheable memory -or- L1 uncacheable and L2 cacheable memory):

- 1.A load misses the data cache and must cause an eviction of a dirty cacheline.
  - This eviction has to land between #2 and #3.
- 2.Four loads to the same cacheline that miss the data cache. No dependencies on previous loads.
- 3.A memory access that is Strongly Ordered within a few instruction cycles of #2. No dependencies on loads in #2.

**Implication:** If the Data Cache Unit encounters this condition, the load to strongly ordered memory is dropped, never returning the data and thereby, hanging the processor core.

Notes:

- "This issue has only been observed on the 8134x when running hand-tuned focus tests written to specifically reproduce this issue.
- "The only way to exit this condition is to reset the processor core.
- "Independent of L1 data cache operating in write through or write back mode.
- "Independent of L2 cache being present or not.
- "Independent of Bus timings/ratios.

**Workaround:** Two workarounds exist for this issue.

- 1.Convert all "Strongly Ordered Memory" operations into "Device Memory" operations inside the Kernel. Where memory is configured as Strongly Ordered (in the page table, the following bits are set TEX=000b and CB=00b) the memory should be changed to be configured as Device Memory (in the page table, the following bits are set (TEX=010b and CB=00b for non-shared device memory) -or-



(TEX=001b and CB=01 for shared device memory).

Small Page Descriptors cannot specify the TEX attribute. In this case, the TEX attribute will default to 0. If CB=00b is used with Small Page Descriptors, a Strongly Ordered Memory region is created. Therefore, do not use Small Page Descriptors; use Extended Small Page Descriptors instead.

2.This is more of a recovery mechanism (not a workaround) in the unlikely event that does occur. If a lockup does occur, the only way to exit this condition is to reset the processor core. Examining the trace buffer after a reset would give information on the code sequencing (within 16 clock cycles) leading to the lockup. Once identified, code corrections can be made to eliminate the condition as listed in the "Required Conditions" section above that created the lockup.

---

#### 5.15 Errata (FEr#15)

**Type:** Functional Erratum

**Relevant for:** PXA32x - B2, PXA31x - A2, PXA30x - All

**Fixed in:** PXA32x - C0, PXA31x - B1, PXA30x - No Fix

**Errata BTS#:** MP-6398

**Description:** Core: System hangs occur while changing operating points when two back to back reads from internal SRAM, the Static Memory Controller, the Dynamic Memory Controller, System Bus 1/System Bus 2 or between the system buses occur.

**Problem:** Data corruption occurs on the memory switch when back to back reads from internal SRAM, SMC, DMC, System Bus 1/ System Bus 2, or between the two system buses occur while the controller clock or bus frequencies are changing (ACCR[SFLFS], ACCR[SMCFS], ACCR[DMCFS], or ACCR[HSS]). Both reads must be from the same controller or bus, and the corresponding clock must be changed during the first read cycle. The second read will be missed by the switch which will cause the switch to stall while waiting for the read data.

**Implication:** The data corruptions will result in system hangs.

**Workaround:** Software must ensure that no more than one read is occurring from these controllers or buses while changing operating points where the ACCR register is programmed to change the controller frequencies. This issue has only been seen during internal testing and has not occurred under a full operating system.

---

#### 5.16 Errata (FEr#16)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5887, ML-792, MLV-1345

**Description:** PIN CONTROL: Glitches can occur when entering low power mode (S0/D1/C2, S0/D2/C2 and S2/D3/C4)

**Problem:** Because of a race condition within the low-power-mode control muxes, a glitch might occur when entering or exiting low-power modes.

**Implication:** The glitch can occur on any signal that uses the MFPR.

**Workaround:** See below:

- 1.Set SLEEP\_SEL for all signals at the same time that the MFPR is programmed. SLEEP\_SEL can be left at 1.
- 2.Once all signals have been configured, RDH can be released. The boot ROM will clear the SLEEP\_SEL bit of any pins it needs when exiting reset, while leaving RDH set.



---

5.17 **Errata (FEr#17)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5837

**Description:** PIN CONTROL: Signals can glitch while entering a hardware or GPIO reset

**Problem:** During a reset, the SMC is reset before the pads are disconnected.

**Implication:** During a reset the SMC non-EMPI control signals may glitch, including nCS2, nCS3, and nWE. This can cause problems with external devices that cannot tolerate the glitches. For example, external SRAM or CPLDs. Because flash memory requires a sequence of commands, it is not affected by the glitches.

**Workaround:** Gate problematic signals with nRESET\_OUT to prevent glitch propagation.

---

5.18 **Errata (FEr#18)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5911, ML-810, MLV-1397

**Description:** PIN CONTROL: Signals can glitch when a BATT\_FAULT occurs.

**Problem:** During a BATT\_FAULT, the APMU gets reset at the same time it is trying to turn off power and disconnect the pads.

**Implication:** Any signal could potentially glitch during a BATT\_FAULT entry.

**Workaround:** None

---

5.19 **Errata (FEr#19)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5892, ML-763, ML-793

**Description:** CLK: Ring oscillator frequency may go out of spec leading to UART failures.

**Problem:** A frequency stability glitch occurs on the outputs of the ring oscillator clock causing the UART clock to be out of spec on slow and fast corners at cold and hot temperatures when the ring oscillator is recalibrating.

**Implication:** Clock instability in S0/D0CS/C0 causes random UART failures when running at higher baud rates. This instability limits the maximum guaranteed supported UART baud rate in S0/D0CS/C0 to 12 Kbps

**Workaround:** None. Limiting VCC\_MVT to 1.85 V reduces the possibility of these failures across temperature changes.

---

5.20 **Errata (FEr#20)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5494, ML-679, MLV-1076

**Description:** PMU: When leaving S3/D4/C4, command to reset the voltages not sent to PMIC.

**Problem:** When leaving S3/D4/C4, the PWR\_I2C does not send out register writes to the PMIC to reconfigure the voltage level.

**Implication:** After exiting S3/D4/C4, there is a slightly higher than normal power consumption since the PMIC is driving the voltages higher than expected.

**Workaround:** After exiting S3/D4/C4, perform a dummy frequency-change sequence to the S3/D4/C4 exit routine.

---

This frequency change must be to the reset state frequency that requires voltage level 0. After this frequency change, perform the frequency change to the targeted frequency/voltage.

### 5.21 Errata (FEr#21)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5308, ML-616, MLV-989

**Description:** PMU: When ACCR[PCCE] = 1 the AGENP[RO\_ST] (MP-6377) may not reflect the correct status of the 120 MHz ring oscillator.

**Problem:** When leaving S0/D0CS/C0 mode the ring oscillator does not get disabled, and the two ring oscillator status bits (AGENP[RO\_ST] and OSCC[ROS]) may not show the same status settings.

**Implication:** The ring oscillator may be in a different status than expected, and may not become disabled when software sets the AGENP[RO\_CTRL] bit.

**Workaround:**

1. After exiting S0/D0CS/C0 mode (ASCR[R0\_S] = 0) read OSCC[ROS] and AGENP[RO\_ST] registers
2. If OSCC[ROS] = AGENP[RO\_ST] = 1
  - Set the AGENP[RO\_CTRL] bit to 1
3. If OSCC[ROS] and AGENP[RO\_ST] are not equal.
  - Set the AGENP[RO\_CTRL] bit to 1
  - Wait until AGENP[RO\_CTRL] bit is cleared to 0
  - Set the AGENP[RO\_CTRL] bit to 1

### 5.22 Errata (FEr#22)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA31x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6387, MLV-1974, ML-1114

**Description:** APMU: System hangs may occur when three separate operations execute between the Application Subsystem Power Management Unit (APMU), Application Subsystem Clock Control Unit (ACCU) OS Timers (OST), and Intel XScale® core.

**Problem:** Data corruption can occur when two overlapping events within the APMU are closely followed by a read from the Intel XScale® core. The Intel XScale® core reads are reads to any register within the ACCU, APMU, or OST. The events within the APMU can come from any of the following three sources.

1. Intel XScale® core writes to the OS Timer Status Register (OSSR) or Application Subsystem Interrupt Control/Status Register (AICSR) registers
2. OST Match Event occurs and the OSSR register is written to clear the status bit(s) for the corresponding timer while the OS Timer Interrupt is enabled (OS Timer Interrupt Enable Register (OIER)).
3. The ACCU writes to the AICSR register in response to a Frequency Change (FCIS), Power Mode Change (PCIS) or a Temperature Induced Frequency Change (TCIS) while the interrupts are enabled (FCIE, PCIE and TCIE)

**Implication:** Data corruption will result in system hangs when the two overlapping writes and the register read occur within the following timing windows. [Figure 1](#) and [Figure 2](#) a diagram showing the series of events that

must happen within the APMU for system hangs to occur.

- Back to back OST match events occur less than 350 ns apart
  - Register read occurs any time between the first interrupt request and the second interrupt request.
- OST match event occurs less than 350 ns from a ACCU interrupt request
  - Register read occurs any time between the first interrupt request and the second interrupt request.
- Write to one of the OSSR/AICSR registers is less than 550 ns from the interrupt request from the OST and a register read occurs during the second interrupt
  - May occur when using any number of OST match event interrupts
  - Register write may occur during first Interrupt Service Routine before the second OST Match event occurs
- Write to one of the OSSR/AICSR registers is less than 550ns from the interrupt request from the ACCU and a register read occurs during the second interrupt.

**Workaround:**

- There are two independent workarounds when using a single OST Match event depending on which timers are being used and how they are being used.

- **When using a single OS Timer.**

1. The following steps are recommended when using an OS Timer where the counter continues to run after a match event or the counter register is not reset after a match event occurs ( $OSMRx[R] = 0$ )
  - The ACCU frequency change interrupts ( $AICSR[xCIE]$ ) must be disabled and XScale core writes to the AICSR register to clear status bits are prohibited
  - Software must ensure that the XScale core writes to the OSSR register cannot overlap with the OST match event interrupt request.
    - Only write the OSSR to clear the Interrupt Status bit in the OST Match Event Interrupt Service routine.
  - Software must ensure the next Match Event interrupt request is at least 350ns from the previous event.
    - Reloading the OSMRx Register for the next Match event based off the current Match register value ( $OSCR0$ ) is recommended.


2. When using a single OS Timer 4 – 11, the following procedures are recommended to ensure that no overlapping APMU events occur from any source when the Periodic Timer stops incrementing after a match is detected ( $OSMRx[P] = 0$ ) or when the OSCRx register is reset after a match occurs ( $OSMRx[R] = 1$ ).
  - The ACCU Frequency Change interrupts ( $AICSR[xCIE]$ ) must be disabled and XScale core Writes to the AICSR register to clear status bits are prohibited.
  - Software must ensure that XScale core Writes to the OSSR register cannot overlap with the OST Match events.
    - Only write the OSSR to clear the Interrupt Status bit in the OST Match Event Interrupt Service Routine.

- **When using a multiple OS Timers**

3. Marvell recommends using a single Match Event architecture along with the Operating System Scheduler for systems requiring multiple event timers.
  - The OS Scheduler replaces additional timers with a lightweight thread that creates separate intervals. These intervals are created by the call `Sleep()`.

4. For systems that must use multiple OS timers, follow these recommended steps to avoid the failure window.
- The ACCU Frequency Change interrupts (AICSR[xCIE]) must be disabled and XScale core Writes to the AICSR register to clear status bits are prohibited.
  - Software must ensure that the XScale core writes to the OSSR register cannot overlap with the OST Match Event interrupt request.
    - Only write the OSSR to clear the Interrupt Status bit in the OST Match Event Interrupt Service Routine
  - **Software must only use OS Timers 4 – 11 with a 32KHz Counter resolution.**
  - OMCRx[CRES] = 0b001, 0b010 and 0b011).
  - All other OMCRx[CRES[3:0]] values are not allowed
  - Software must ensure that ACCU, APMU or OST register reads are issued outside the failure windows
  - Software must ensure the next match event interrupt request is at least 350ns from a previous match event interrupt request.
    - Software should enable the Automatic OSCRx Reset (OSMRx[R] = 1) or disable the OSCRx incrementing after reset (OSMRx[P] = 0)
  - Using OSCRO along with OSMR3 to generate watchdog resets allowed.
5. For systems needing to use multiple OST 0 – 3 timers the following steps are recommended to avoid the failure window.
- The ACCU frequency change interrupts (AICSR[xCIE]) must be disabled and Xscale core writes to the AICSR register to clear status bits are prohibited.
  - **Software must not use OS Timers 4 – 11.**
  - Software must ensure that the XScale core writes to the OSSR register cannot overlap with the OST Match Event writes to the OSSR.
    - Only write the OSSR to clear the interrupt status bit in the OST Match Event Interrupt Service Routine
  - Software must ensure the next Match Event interrupt request is at least 350ns from a previous Match Event interrupt request.
  - Software must ensure that ACCU, APMU or OST register reads are issued outside the failure windows. The following procedures are recommended to avoid having a read issued during the failure window.
    - After write to the OSSR register to clear the interrupt status bits software must issue reads to the Services Power Management Scratch Pad Register (PSPR) before reading any APMU, ACCU, or OST registers. The following instructions are recommended for the OST Interrupt Service Routine for clearing the OST status registers and avoiding having a read fall within the failure window.
      - Write OSSR – clear interrupt pending status bits.
      - Data Memory Barrier Instruction (DMB)
      - Read PSPR
      - Data Memory Barrier Instruction (DMB)
      - Read PSPR
      - Data Memory Barrier Instruction (DMB)
  - Using OSCRO along with OSMR3 to generate watchdog resets allowed.


**Figure 1: Single OS Timer Match Event with an OSSR Write failure window**



**Notes**

- $t_{WRITE}$ : Register write request
- $t_{INT}$ : duration of interrupt service request (100 ns - 200 ns)
- $t_{WINDOW}$ : Time between OSSR/AICSR write and the interrupt request. To avoid failure window must be greater than 550 ns.
- $t_{READ}$ : Time which the ACCU/APMU/OST read request must be received

**Figure 2: Multiple OS Timer Match Event**



**Notes**

- $t_{INT1}$ : duration of first OST ISR. (200ns)
- $t_{INT2}$ : duration of second OST ISR (100ns)
- $t_{WINDOW}$ : Time between the back to back interrupt requests. To avoid failure window must be greater than 350ns +  $t_{INT1}$
- $t_{READ}$ : Time which the ACCU/APMU/OST read request must be received



---

**5.23 Errata (FEr#23)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6392, MLV-2000, ML-1117

**Description:** APMU: Any Writes to the Application Subsystem Interrupt Control/Status Register (AICSR) register clear the interrupt status bits.

**Problem:** The AICSR register is a "write 1 to clear" register but any writes to this register clear all status bits.

**Implication:** Software cannot clear the single status bit which can cause other interrupt bits to be cleared unintentionally.

**Workaround:** Do not use the AICSR register for frequency or Power mode changes.

---

**5.24 Errata (FEr#24)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5014, ML-547, MLV-898

**Description:** SERVICES: GPIO reset wakes up the processor from S3/D4/C4.

**Problem:** If a GPIO reset is detected before services completes an S3/D4/C4 entry, the reset is treated as a wake up. The processor enters S3/D4/C4 but exits right away and the following register status is observed: ARSR[LPMR]=1, AD3SR=0, PWSR=0, PSR[SS3S]=1  
Note: S3/D4/C4 entry only occurs through BATT-FAULT.

**Implication:**

**Workaround:** Based on the above register bit combinations, it is possible to deduce that the part entered S3/D4/C4 and exited due to a GPIO reset.

---

**5.25 Errata (FEr#25)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-4797

**Description:** SERVICES: Unexpected PWR\_I2C commands sent on ACCR write.

**Problem:** When writing the ACCR but not setting the T- or F-bits, an unexpected PWR\_I2C transaction is sent.

**Implication:** When lowering the frequency, the voltage could be lowered without the core actually changing frequency.

**Workaround:** Always set the F-bit after writing new L/N values to ACCR before setting ACCR for other frequency changes.

---

**5.26 Errata (FEr#26)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5502, MLV-1080

**Description:** SERVICES: Two sets of PWR I<sup>2</sup>C sent on S2 exit.

**Problem:** Two sets of PWR I2C commands are sent during S2 exit.

**Implication:** Boot continues after the first set of commands are sent. Code is being fetched during the second set of

---

commands.  
**Workaround:** None

---

**5.27 Errata (FEr#27)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5961  
**Description:** SERVICES: nRESET\_IN ignored during start-of-day when VCC\_BBATT is less than 2.4V.  
**Problem:** During the start-of-day power supply ramp for VCC\_BBATT, the nRESET\_IN signal is blocked when VCC\_BBATT is less than 2.4V.  
**Implication:** Resets during start-of-day may be ignored.  
**Workaround:** If resets are possible while VCC\_BBATT is ramping, ensure they are held until VCC\_BBATT is greater than 2.4V. VCC\_BBATT must be drained to 0V when the voltage level drops below 2.4V.

---

**5.28 Errata (FEr#28)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-6158  
**Description:** SERVICES: SRAM is not retained during a GPIO RESET, and the Boot ROM resumes to SRAM in Non-debug mode.  
**Problem:** In Non-debug mode, the Boot ROM resumes to internal memory after a GPIO reset. However, the SRAM is not retained during a GPIO reset.  
**Implication:** System may lock up after a GPIO reset if the SRAM loses state.  
**Workaround:** None

---

**5.29 Errata (FEr#29)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-6187  
**Description:** SERVICES: Lockup occurs if nBATT\_FAULT asserted after sys\_Del count is done and the battery does not have enough energy to complete Start-of-Day sequence.  
**Problem:** There is a window during the start-of-day sequence, after the sys\_del counter is done, if a BATT\_FAULT occurs during the window and the power supplies shut down (except for VCC\_BBATT), the part locks up.  
**Implication:** Once the part locks up, applying power again does not recover the device.  
**Workaround:** There are two workarounds for this problem:

1. Drain VCC\_BBATT after the lockup occurs. For end-customers, this approach may require removing the main battery and waiting for the supercap to drain. For designs using a backup battery, Option #2 is the only workaround.
2. Cause a nRESET assertion after applying main power. This approach would require an nRESET button to be accessible to end-use customers.

### 5.30 Errata (FEr#30)

**Type:** Functional Errata

**Relevant for:** PXA32x - B2, PXA31x - A2, PXA30x - All

**Fixed in:** PXA32x - C0, PXA31x - B1, PXA30x - No Fix

**Errata BTS#:** MLV-1902, ML-1128

**Description:** SERVICES: System hangs may occur when increasing operating points from 208 MHz or 416 MHz, or when using 806 MHz or 416 MHz Idle modes.

**Problem:** Random system lockups may occur when the XScale® core PLL is relocked. The failure is seen more often when performing frequency change stress tests for a varying length of time. This failure is seen in the following states.

1. Increasing frequency from either 208MHz (XL = 16; XN = 1) or 416 MHz (XL=16; XN = 2).
2. Core enters 806 MHz or 416 MHz Idle modes

**Implication:** Systems may intermittently lock up under very specific circumstances. Evaluation of this lockup has determined that the issue has been seen when:

- The operating point being increased to has a Turbo-mode to Run-mode ratio of 2:1 (XN =2).
- The processor is placed in Idle mode (Write to PMRMODE register) with XL = 16 and XN = 2 (416 MHz run)
- The ACCR[XL] = 16 before the frequency change.
- There is an operation that involves a PLL relock or the PLL divisors are changed
- Once a lockup has occurred the system must be reset
- The following operating point changes may intermittently cause a lock-up.
  1. 208 MHz -> 416 MHz
  2. 208 MHz -> 624 MHz
  3. 416 MHz -> 624 MHz

**Workarounds:** There are two different workarounds, one for changing frequencies (#1) and one for avoiding 416 MHz Idle lock-ups (#2)

**Workaround #1:** When increasing the operating point (core frequency), software must first switch the core frequency to 104 MHz (XL = 8; XN = 1) before switching to the higher operating point. Changing the ACCR bus frequencies to match the 104 MHz operating point is not required. The following steps must be followed when increasing operating points:

1. Disable hardware voltage-change commands to the PMIC by clearing the PVCR[PVE] and PVCR[FVE]. Disable any software voltage change commands when using software to change voltages.
2. Set ACCR[XN] = 1, ACCR[XL] = 8 and ASCR[MTS] = 1 for 104 MHz.
3. Set the XCLKCFG[F] and XCLKCFG[T] bits to 1 to initiate the frequency change.
4. Re-enable the hardware voltage-change commands to the PMIC by setting the PVCR[PVE] and PVCR[FVE] bits to 1. Re-enable software voltage change commands when using software to change voltages.
5. Set the ACCR[XN] and ACCR[XL] and ASCR[MTS] for the new operating point.
6. Set the XCLKCFG[F] and XCLKCFG[T] bits to 1 to initiate the frequency change.
7. Set the remaining ACCR register values to configure the correct bus frequencies for the new operating point.

**Workaround #2:** There are four possible replacements for 806 MHz or 416 MHz idle modes and 1 possible workaround



if the system hangs when using 806 MHz or 416 MHz Idle modes:

1. Use a software-based Idle Replacement routine. When there are no tasks to run, use a While-loop to wait for the next interrupt.
  - This workaround has the lowest latency, but power savings are minimal.
2. Use 104 MHz IDLE as a replacement for 806 or 416 IDLE. The software flow is:
  1. Determine there are no tasks and decide to go to Idle.
  2. Switch to 104 MHz Run mode (XL = 8 and XN = 1).
  3. Issue a PWRMODE command to place the core into Idle.
  4. When an interrupt occurs to return the processor to Run mode, switch to 416 MHz Run mode. Switching to 104 MHz incurs a ~30  $\mu$ s delay going to 104MHz and a 30  $\mu$ s delay upon resume before code is running at 416MHz. This workaround has better power savings, but higher latency on Resume.
3. Use 208 MHz (XL=16; XN = 1) IDLE as a replacement for 806 MHz (XL=31; XN = 2) or 416 MHz (XL=16; XN =2) IDLE. The software flow is:
  1. Determine there are no tasks and decide to go to Idle.
  2. Change the XN = 2 while leaving XL = 16.
  3. Set the XCLKCFG[T] bit to initiate a Turbo mode change.
  4. Issue a PWRMODE command to place the core into Idle.
  5. On Resume from Idle, keep running at 208 MHz Run mode.
  6. At the next power management evaluation event, change the frequency to 416 MHz if required. This gets to power-saving IDLE fast and has low-latency to running code at 208 MHz
4. Use S0/D0CS/C0 run as an Idle replacement. S0/D0CS/C0 run has low power operation, but some peripherals don't run in S0/D0CS/C0 and peripheral clock dividers must be changed (LCD refresh, audio, etc.)
  - Resume latency is ~60  $\mu$ s
  - This flow is the recommended flow for lowest power IDLE. This is part of the power management software provided by Marvell.
5. As a workaround, when using 806 MHz or 416 MHz Idle modes, implement a watchdog timer reset that resets the processor in the event of a system hang.

---

### 5.31 Errata (FEr#31)

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-3721

**Description:** 1-WIRE: Reads bad data when Receive-Buffer-Full status bit is set.

**Problem:** The W1INTR[RBF] flag is set when there is a byte waiting to be read in the Receive buffer. Data then read from the Receive buffer after this flag is set is bad data. The problem happens because the Rx Buffer status bit gets set too soon.

**Implication:** Incorrect data can be received.

**Workaround:** Wait a minimum of 2  $\mu$ s before reading to receive valid data.



---

**5.32 Errata (FEr#32)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-3751

**Description:** 1-WIRE: PD flag not cleared when read (when interrupts are disabled).

**Problem:** If interrupts are disabled and W1IER[IAS] bit is cleared, the W1INTR[PD] bit field does not get cleared. Normally, the W1INTR[PD] flag is cleared regardless of whether the interrupts are enabled or disabled.

**Implication:**

**Workaround:** Set the W1IER[EPD] bit and the W1IER[IAS] bits.

---

**5.33 Errata (FEr#33)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-2628

**Description:** INTERRUPT CONTROLLER: Unexpected exception vector when ICCR[DIM]=0 and ICMR=0.

**Problem:** When ICCR.DIM = 0 and ICMR = 0 and a direct key press is performed, the Interrupt Control IRQ Pending (ICIP) Register does not indicate a pending interrupt after coming up from idle, but the core attempts to vector to an exception-vector address (0x000 to 0x01C).

**Implication:** If ICMR=0x0, ICCR[DIM]=0b0, and a direct key press is performed, then the *correct* behavior is as follows:

After the key is pressed, the processor wakes from Idle, ICPR gets updated, the ICIP (or ICFP) does not get updated, and the processor should *not* vector to any vector address (0x00 to 0x1C).

The *incorrect* behavior is:

After the key is pressed, the processor wakes from Idle, ICPR gets updated, the ICIP (or ICFP) does not get updated, but the processor tries to vector to 0x18 (for IRQ handler) or 0x1C (for FIQ handler), based on the contents of ICLR.

Keypad and DIM bit and ICMR test failure:

```
ICCR = 0x00000000, ICMR = 0x04000000.  
KPC = 0x000001C3; KPC[DIE] = 1; KPC[DE] = 1;  
KPKDI[DIRECT KEY DEBOUNCE INTERVAL] = 20 (ms).
```

**Workaround:** The code below disables interrupts to the core before going to idle and re-enables core interrupts after returning from Idle.

```
IDLE:  
.global IDLE  
mrs r0, cpsr @ read current processor status register  
orr r0, r0, #0xC0 @ disable core interrupts  
msr cpsr_c, r0 @ update the current processor status register  
mov r0, #1  
mcr p14, 0, r0, c7, c0, 0 @ Set IDLE  
mrc p14, 0, r0, c7, c0, 0 @ CPWAIT ROUTINE  
mov r1, r1 @ CPWAIT ROUTINE  
sub pc, pc, #4 @ CPWAIT ROUTINE
```

```
mrs r0, cpsr @ read current processor status register
bic r0, r0, #0xC0 @ enable core interrupts
msr cpsr_c, r0 @ update the current processor status register
mov pc, r14 @ RETURN
```

---

**5.34 Errata (FEr#34)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5070

**Description:** RTC: Wristwatch alarm does not interrupt at the correct time of day

**Problem:** Wristwatch alarm does not interrupt at the preferred time of day.

**Implication:**

**Workaround:** The Wristwatch Alarm registers RYARx must be programmed before RDARx is set.

---

**5.35 Errata (FEr#35)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5015

**Description:** OST: Extra count after match when the Match Control registers are set.

**Problem:** If both Match Control registers, OMCRx[R] and OMCRx[P], are set, the counter starts at 0x0000\_0000 and increments at the frequency of the channel clock until OSCRx matches the value programmed in OSMRx. However, when this occurs in Low-power modes, one additional timer count occurs.

**Implication:** This issue occurs in Low-power modes, when both the count frequency and the module clock frequency are 32 kHz. Once a match is detected, only in the next clock cycle is the interrupt set and counting stops. This results in one additional 32 kHz clock delay in signalling the interrupt and resetting OSCRx.

**Workaround:** Program OSMR value one less than the preferred count value, when a timer channel using 32 Kbyte clock is to be used as a wakeup source.

---

**5.36 Errata (FEr#36)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-4558

**Description:** DMC: Writes to uninitialized memory can hang the system.

**Problem:** When debugging BSPs, there are times when a wrong or undefined pointer reads/writes from/to and undefined memory location. On the PXA3xx (88AP3xx) Processor Family, this occurs at an address above 0x80000000.

**Implication:**

**Workaround:** Initialize the memory controller before attempting to write to memory.

---



---

**5.37 Errata (FEr#37)**

**Type:** Functional Errata

**Relevant for:** PXA30x-A1

**Fixed in:** No Fix

**Errata BTS#:** ML-982

**Description:** DMC: DDR failures occur at VCC\_APPS <= 975 mV.

**Problem:** The DMC thinks the previous bank/row has been closed and never issues a precharge command to close the previous bank/row. The Next Active command to that bank is ignored and the previous row is accessed for the current transaction, leading to data corruption that may include system hangs when software is running out of DDR.

**Implication:** System hangs and/or data corruption may occur when accessing the DDR at VCC\_APPS <= 975 mV.

**Workaround:** Power management software must ensure that VCC\_APPS is greater than 975 mV across all process and temperature variations. When using the hard-coded PWR\_I2C commands, the VCC\_APPS Voltage Control Register (AVCR) requires programming to adjust the voltage in 25 mV increments to ensure VCC\_APPS is always above 975 mV. If the hardware driven PWR\_I2C commands are not being used, software must issue I<sup>2</sup>C commands to the PMIC to adjust the VCC\_APPS voltage.

---

**5.38 Errata (FEr#38)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5608

**Description:** SMC: When using DMA and the ALT bit in the Address Configuration Registers (CSADRCFGx) is set to 0b00 or 0b01 corruption occurs on the bus.

**Problem:** When using the SMC with DF\_SCLK equal to or greater than 52 MHz and no setup time while running DMA channels, the data stays on the DFIO bus when LUA is supposed to be on the bus. This issue does not occur at 20 MHz or when there is 1 cycle of setup time.

**Implication:** SMC accesses are corrupted.

**Workaround:** Either run SMC at a slower frequency or allow 1 cycle of setup time (ALT = 0b10 or 0b11).

---

**5.39 Errata (FEr#39)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6154

**Description:** SMC: Last LUA of PCMCIA transaction always has the ALW bit in the Address Configuration Registers (CSADRCFGx) set to 1.

**Problem:** Regardless of ALW setting, the last LUA of any PCMCIA transaction (where both chip selects are de-asserted) always has an ALW of 1.

**Implication:** ALW setting will not be correct on the last LUA.  
**Workaround:** This problem occurs only when ALT=0b00 or 0b10. Use ALT=0b01 or 0b11 instead.

---

**5.40 Errata (FEr#40)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5991

**Description:** SMC: If MECR[CIT] is 0, a Read/Write to the PC card memory space hangs.

**Problem:** If CIT remains at 0, and an unintended access occurs to the PC card memory space, then the processor hangs because the switch does not receive the data transaction from the SMC.

**Implication:** Unintended accesses to the PC card memory space cause hangs.

**Workaround:** Do not access PC card unless PC card is present.

If this cannot be guaranteed by software, set CIT=1 and program the GPIO8 pin to not be nPWAIT.

---

**5.41 Errata (FEr#41)**

**Type:** Functional Errata

**Relevant for:** PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** ML-700

**Description:** NFC: Sequential row Reads do not read data correctly with 16-bit NAND.

**Problem:** During a sequential row Read of 16-bit NAND, the data is not latched in the correct locations, possibly being offset.

**Implication:** Incorrect data and/or ECC received from NAND flash.

**Workaround:** 8-bit NAND works correctly. Do not use SRR with 16-bit NAND. Instead, use multi-page Reads supplying the address every time.

---

**5.42 Errata (FEr#42)**

**Type:** Functional Errata

**Relevant for:** PXA30x-All, PXA31x-All

**Fixed in:** No Fix

**Errata BTS#:** ML-887, MLV-1593

**Description:** NFC: NAND timing sensitivity on the clocks feeding the NFC registers.

**Problem:** NAND failures using both DMA and non-DMA modes.

**Implication:** Causes data corruption.

**Workaround:** Restrict software from writing to NFC registers (NDCR, NDTR0CS0, NDTR1CS0, NDSR, NDBDR0, NDBDR1) while the NAND clock is enabled. SMC transactions are also prohibited while the NAND clock is disabled. The following workarounds are recommended by Marvell when using the NFC.

- Writing to the NDTR0CS0, NDTR1CS0, and NDREDEL registers is recommended when initially configuring the NFC. The NDCR should also be programmed initially to configure the NFC. The NDCR[ND\_RUN] bit must be written to during run time. These registers can be written to outside of the initial configuration as long as the same clock gating procedures are used.

**Configuration register function:**

1. Disable Core Interrupts (Core Program Status Register (CPSR)).
  2. Issue the Data Write Buffer (DWB) command to flush the memory Writes.
-



3. Issue the Data Memory Buffer (DMB) command to flush the memory data.
4. Flush the SMC queue (only required when SMC transactions are possible).
5. Disable NFC\_CLK (D0CKEN\_A[CKEN[4]] = 0).
6. Write registers NDTR0CS0, NDTR1CS0, NDCR and NDREDEL.
7. Enable NFC\_CLK (D0CKEN\_A[CKEN[4]] = 1).
8. Enable Interrupts (Core Program Status Register (CPSR)).

- Writing to the NFC command (NDCBx) and Status registers (NDSR) programs the NFC for NAND accesses. These procedures are used every time the NFC is used to access the NAND device. DMA is not allowed for these registers.

**Command register function:**

1. Ensure the NFC is not currently running (NDCR[ND\_RUN] = 0).
2. Disable Core Interrupts (Core Program Status Register (CPSR)).
3. Issue the Data Write Buffer (DWB) command to flush the memory Writes.
4. Issue the Data Memory Buffer (DMB) command to flush the memory data.
5. Flush the SMC queue (only required when SMC transactions are possible).
6. Disable NFC\_CLK (D0CKEN\_A[CKEN[4]] = 0).
7. Enable the NFC by setting the NDCR[ND\_RUN] to 1.
8. Wait for the Write Command Request Status Register (NDSR[WRCMDREQ]) to be set to 1.
9. Clear the NDSR[WRCMDREQ] by writing a 1.
10. Write to the NDCB0, NDCB1 and NDCB2 Command registers.
11. Enable NFC\_CLK (D0CKEN\_A[CKEN[4]] = 1).
12. Enable Interrupts (Core Program Status Register (CPSR)).

DMA can be used to configure one data stream at a time for Reads and Writes to the NAND Controller Data Buffer (NDDB) without disabling the NFC clock.

---

**5.43 Errata (FEr#43)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-817

**Description:** MMC/SD/SDIO: CS de-assertion/re-assertion timing.

**Problem:** The SD and MMC specs require a multiple of eight cycles between CS de-assertion and re-assertion. PXA3xx (88AP3xx) Processor Family processors do not follow this requirement.

**Implication:** Cannot de-assert and re-assert CS.

**Workaround:** Two workarounds exist:

**Workaround #1:** Do not de-assert/re-assert a CS.

**Workaround #2:** Reset the card between CS de-assertion and CS re-assertion.

---

**5.44 Errata (FEr#44)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-4636

**Description:** MMC/SD/SDIO: MMC does not detect CRC errors or missing stop bit.

**Problem:** During a card eject, invalid command responses and Read data blocks may not be detected by the MMC

controller.

**Implication:** The result is corrupted data.

**Workaround:** Ensure that the Card Insertion Detect bit is connected to PXA320 processor so that software detects when the card is ejected and not attempt any card accesses. Also ensure that there are pullups on MMC-MD and MMDAT<3:0> so that these signals are inactive when the card is ejected.

---

**5.45 Errata (FEr#45)**

**Type:** Functional Errata

**Relevant for:** PXA32x - B2

**Fixed in:** No Fix

**Errata BTS#:** MP-6233

**Description:** MMC: MMC\_CLK glitch in S0/D0CS/C0.

**Problem:** MMC\_CLK glitches when MMC\_CLKRT[CLK\_RATE] = 0b010 (/4).

**Implication:**

**Workaround:** Restrict software from using MMC\_CLKRT[CLK\_RATE] = 0b010 when in S0/D0CS/C0. MMC\_CLKRT[CLK\_RATE] = 0b000 and 0b001 work correctly.

---

**5.46 Errata (FEr#46)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-4985

**Description:** LCD: Data not correct from Overlay 2 in YCbCr 4:2:0 mode.

**Problem:** During a simulation, the LCD occasionally sends out the CbCr pixel twice.

**Implication:** Incorrect data displayed on the screen for one frame. This issue has never been seen in a full system, and is also present on the Marvell® PXA27x processor.

**Workaround:** None.

---

**5.47 Errata (FEr#47)**

**Type:** Functional Errata

**Relevant for:** PXA30x-All, PXA31x-All

**Fixed in:** No Fix

**Errata BTS#:** ML-1003

**Description:** LCD artifacts occur when exiting S0/D1/C2.

**Problem:** On exit from S0/D1/C2, software enables the LCD controller, which enables the LCD\_FCLK. An LCD\_FCLK glitch is observed to be between 10 µs to 45 µs.

**Implication:** A glitch duration close to or greater than 45 µs can cause visual artifacts on the screen when exiting from S0/D1/C2.

**Workaround:**

1. Disable the LCD controller by clearing the LCCR0[DIS] bit.
2. Wait for LCSR0[LDD] bit to be set signaling that the LCD controller has been disabled.
3. Disable the LCD clock by clearing the D0CKEN\_A[CKEN[1]] bit.
4. Enable the LCD controller by setting the LCCR0[ENB] bit.
5. Enable the LCD clock by setting the D0CKEN\_A[CKEN[1]] bit.
6. Enter S0/D1/C2.
7. Exit S0/D1/C2.

Program the LCD Descriptors in the FDADR0 register only.

---



---

**5.48 Errata (FEr#48)**

**Type:** Functional Errata  
**Relevant for:** PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MLV-1768  
**Description:** LCD: VGA screens not supported when using S0/D1/C2 mode.  
**Problem:** There is not enough internal SRAM to hold the Frame buffer for a VGA display.  
**Implication:** VGA screens are not able to refresh when using S0/D1/C2 mode.  
**Workaround:** None

---

**5.49 Errata (FEr#49)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - B2, PXA30x - All  
**Fixed in:** PXA32x -C0, PXA30x - No Fix  
**Errata BTS#:** MP-6346  
**Description:** LCD: Insufficient bandwidth to support 640x480 screens when using DDR for the Frame buffer in S0/D0CS/C0 mode.  
**Problem:** The DDR frequency (15 MHz) is too slow to support refreshes in S0/D0CS/C0.  
**Implication:** Artifacts appear on the LCD screen when using S0/D0CS/C0 mode.  
**Workaround:** Use internal SRAM for the Frame buffer when using larger screen sizes when using S0/D0CS/C0 mode.

---

**5.50 Errata (FEr#50)**

**Type:** Functional Errata  
**Relevant for:** PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MLV-2179  
**Description:** LCD: The MSB acts as both the T-bit and red color when using RGB565 with Chroma Keying enabled on Overlay 1 and Overlay 2.  
**Problem:** When Overlay 1 or Overlay 2 are configured for RGB565 with Chroma Keying enabled, the MSB of pixel data acts as both the T-bit and the red color.  
**Implication:** Chroma keying for Overlay 1 and Overlay 2 does not work properly with RGB565.  
**Workaround:** For Overlay 1, the following workaround is used to enable Chroma keying in Overlay 1. For Overlay 2, Chroma Keying is not supported.

- LCCR3[PDFOR] = 0b00
- LCCR4[PAL\_FOR] = 0b00
- LCCR4[K1] = 0b111
- LCCR4[K2] = 0b111
- LCCR4[K3] = 0b111

---

**5.51 Errata (FEr#51)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-2742  
**Description:** CI: CGC LUT load gets corrupted due to READ/WRITE pointer collision.  
**Problem:** If a single Descriptor is used to fill the camera LUT, the fill occurs too fast and the data can't be transferred from the FIFO to the LUT in time.

---



**Implication:** Unknown data would be loaded into the camera LUT.  
**Workaround:** If the Descriptor that loads the LUT is split into six non-chained (since chaining on this FIFO is \*not\* supported) with each Descriptor transferring 32 bytes, there seems to be enough time to prevent collisions described earlier. Also, the Descriptors are loaded in IM for fastest access.

Programming flow:

0. Load IM with 192 bytes of data to be loaded into LUT
1. Program Descriptor in IM with burst size of 32
2. Program CIDADR3 (in CI unit to reflect Descriptor address)
3. Issue a blocking read to a non-DMA related register
4. Idlecycle for 100 cycles
5. Go back to 1 till all 6 Descriptors are completed.
6. Once last Descriptor has been programmed and is in execution, wait on CICCR[19] to reflect status of LUT load completing.

---

#### 5.52 Errata (FEr#52)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-4550, ML-710  
**Description:** CI: Camera FIFO overflow when slow memory accesses occur.  
**Problem:** When there is a long VLIO or SMC transaction occurring on the system bus, the camera can become starved and overflow its FIFOs.  
**Implication:** Incorrect capture information on high-bandwidth cameras.  
**Workaround:** Do not allow long VLIO or SMC transactions during high-bandwidth camera activity.

---

#### 5.53 Errata (FEr#53)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5469  
**Description:** CI: Scaling unit computes bad values for Y value of YCrCb scaling.  
**Problem:** When performing 2:1 scaling, the Y data in the image is not correct. The hardware does  $(Y1+2Y3+Y5)/4$  for odd and  $(Y2+2Y4+Y6)/4$  for even pixels. It should do  $(Y1+2Y2+Y3)/4$  for odd and  $(Y3+2Y4+Y5)/4$  for even.  
**Implication:** There are some imaging artifacts on rescaled pictures.  
**Workaround:** Use the GCU to rescale YCrCb images. RAW processing is unaffected.

---

#### 5.54 Errata (FEr#54)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5711  
**Description:** GCU: STR\_BLT instruction hangs when Source and Destination buffers are in external SRAM, does not return correct data occasionally when buffers are in DDR.  
**Problem:** When STR\_BLT attempts to stretch an image larger than 10X along the X axis, the instruction hangs if the Source and Destination buffers are in SRAM. The same test with Source and Destination in DDR occasionally produces incorrect data.



**Implication:** Large stretches performed in external SRAM lock up the GCU. Large stretches in DDR occasionally produce incorrect data.  
**Workaround:** Break up large (greater than 10X) stretches in the X-dimension into batches of smaller stretches.

---

**5.55 Errata (FEr#55)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5916  
**Description:** GCU: Pattern copy fails for random test cases with data mismatch.  
**Problem:** When performing back-to-back pattern copies, the internal state machine does not read the data into the internal scratch-pad memory before writing the data out to the destination.  
**Implication:** Pattern copies can become corrupted.  
**Workaround:** GC\_PATT instructions are not supported in the GCU for the PXA3xx (88AP3xx) Processor Family.

---

**5.56 Errata (FEr#56)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5931  
**Description:** KEYPAD: Wrong clock divider in S0/D0CS/C0 mode is causing keypress detection problems.  
**Problem:** S0/D0CS/C0 mode is clocking the keypad unit at 25 kHz instead of 32 kHz. Keypress debouncing and detection is not reliable in S0/D0CS/C0 mode due to the literal table no longer matching the clock frequency.  
**Workaround:** Multiply the debounce interval by 25/32.

---

**5.57 Errata (FEr#57)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No fix  
**Errata BTS#:** MP-4917  
**Description:** TSI: TSI controller takes almost 2  $\mu$ s to start up after exiting Low-power mode.  
**Problem:** If a conversion is in progress when going to Low-power mode, when exiting Low-power mode, the first conversion data is bad.  
**Implication:** The first conversion after exiting Low-power mode can be incorrect.  
**Workaround:** If a conversion is in progress during a Low-power mode entry, the first conversion after Low-power mode exit must be ignored. Software cannot start a conversion until 52  $\mu$ s after exiting the Low-power mode if the TSI power supply was disabled. If the TSI power supply was not disabled, software must wait 2  $\mu$ s. So the pre-charge delay can be set or a delay can be inserted before starting the conversion.

---

**5.58 Errata (FEr#58)**

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-5647  
**Description:** TSI: Discontinuity in A/D conversions near 64-count boundaries in 12-bit mode.  
**Problem:** Near 64 count boundaries, the TSI shows an intermittent jump down by 64 counts. For example, instead of reading 320, it reads 256. It does not happen continuously; in testing, 3 of 4 points are read correctly.

---

**Implication:** Points from TSI show occasional noise.

**Workaround:** Discard points that occur on the 64-count boundaries (last six bits are 0).

---

**5.59 Errata (FEr#59)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5711

**Description:** TSI exhibits differing conversion times.

**Problem:** The TSI conversion time changes from 1.6 ms/conversion to 0.8 ms/conversion about a third of the way up between 0 and 3.3 V.

**Implication:** Conversion time between points could differ depending on location on the screen.

**Workaround:** The uneven conversion time is caused by the Stylus Detect logic, which controls the ADC delay and Pre-charge delay if the internal logic detects a Stylus detect, regardless of the SD bit. When the logic detects the signal is higher than 1/2 Vcc of the XP signal there is no Stylus detect so the ADC delay and Pre-charge delay are disabled. The uneven conversion time is not caused by actual ADC conversion time.

Ensure XP returns to the same level after each conversion so that the conversions are the same length.

---

**5.60 Errata (FEr#60)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5791

**Description:** TSI: Steady state conversion variability > 4 counts.

**Problem:** When converting a steady value, the ADC typically can vary 4 counts but as many as 7 counts.

**Implication:** The ADC is listed as 12 bits, but with this sighting the resolution is closer to 9 bits.

**Workaround:** Use software to provide a mean value for every 3-5 points to filter problem pixels.

---

**5.61 Errata (FEr#61)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5832

**Description:** TSI: ADCS[RUN] not cleared by TSI state machine

**Problem:** In Single-Conversion mode, the ADCS[RUN] bit is not cleared by the TSI state machine when the conversion finishes.

**Implication:** Read/modify/write operations to the ADCS register cause a new conversion to start.

**Workaround:** After receiving a Conversion-Complete interrupt, clear the ADCS[RUN] bit during read/modify/write operations to the ADCS register.

---

**5.62 Errata (FEr#62)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6029

**Description:** TSI: Stylus-up interrupt not reliably generated when XY=1, CC=0, also generating extra Stylus down/up

---

- interrupts in continuous conversion (XY=1, CC=1).
- Problem:** When using the TSI in Single-Conversion mode, the Stylus-up interrupt can be missed. In Continuous-Conversion mode, extra Stylus-down/up interrupts are received.
- Implication:** Software does not receive an interrupt that the stylus is up.
- Workaround:** Set up a timer that is reset each time a Stylus event is received. When the timer expires without the Stylus-up interrupt, then force a single conversion, which causes a Stylus-up interrupt once the conversion completes.

System initialization:

1. Enable Stylus Detect interrupt.
2. Enable 1  $\mu$ s Timer tick interrupt.
3. last\_tsi\_interrupt = NONE.
4. conversion\_data\_valid = FALSE.
5. stalled\_conversion\_flag = FALSE.

Interrupt handler

```
if (stylus detect == down)
    if (conversion_data_count)
        store conversion data
        conversion_data_valid = FALSE
    disable stylus detect interrupt
    start conversion
    last_tsi_interrupt = stylus_down
if (stylus detect == up)
    discard queued conversion data
    last_tsi_interrupt = stylus_up;
if (conversion complete)
    queue conversion data
    conversion_data_valid = TRUE
    last_tsi_interrupt = conversion_complete
if (timer tick)
    if (last_tsi_interrupt == conversion complete)
        stall counter++
    else
        stall counter = 0
    if (stall counter > 10000)
        start conversion
        stalled_conversion_flag = TRUE
        stall counter = 0
```

---

5.63 **Errata (FEr#63)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6065

**Description:** UDC: FIFO content of an IN endpoint not flushed by FEF when double-buffered

**Problem:** Attempting to flush an endpoint only flushes the inactive FIFO of an IN endpoint.

**Implication:** An endpoint stalled by SET\_FEATURE and cleared by CLEAR\_FEATURE may still have old data in the active FIFO since only the inactive half of the double buffer is cleared. Setting FEF only flushes the second packet in a FIFO, since the first packet is still in the active FIFO.

**Workaround:** None

---

5.64 **Errata (FEr#64)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5596

**Description:** U2DC: Corrupted EOP in Full-speed mode causes the U2D to hang.

**Problem:** The U2DC hangs if a corrupted EOP occurs and is followed by a SE0 longer than specified in the USB 2.0 specification.

**Implication:** Malformed packets lock up the client. This action is not expected to occur in normal operation, and has never been seen on any systems using the U2DC.

**Workaround:** The host controller must send a reset to the U2DC.

---

5.65 **Errata (FEr#65)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5705

**Description:** U2DC: DMA Control/Status register reports "end of Receive" interrupt on "IN" endpoints

**Problem:** Two endpoints configured as BULK\_IN and ISO\_IN are reporting "End of Receive" interrupts. This action should not be possible because these endpoints are not receivers of data. This action occurs during zero-packet IN transfers.

**Implication:** Spurious interrupts on IN endpoints.

**Workaround:** Ignore EOR interrupt status bit on IN endpoints.

---

5.66 **Errata (FEr#66)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5810

**Description:** U2DC: Internal USB host/client resistors may be out of spec above 40 degrees C.

**Problem:** Due to some signals coming from a different clock domain, the internal USB temperature compensation

---



mechanism may work incorrectly above 40 degrees C.

**Implication:** The host/client resistors can be out of spec.

**Workaround:** None.

---

**5.67 Errata (FEr#67)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-3068

**Description:** USBH: USB host Port 3 in Transceiverless mode may not work correctly with an external device.

**Problem:** When placed into Transceiverless mode by setting UP3OCR[CFG] = 2, the USB host Port 3 expects a certain behavior from the attached external device.

While the device is in Receive mode, that is, while USB\_P3\_2 (OE\_n) is de-asserted, the host Port 3 expects the device to transmit a Steady State 1 on the USB\_P3\_6 (VPO) pin and a Steady State 0 on the USB\_P3\_4 (VMO) pin.

**Implication:** .

**Workaround:** Use a 2-input OR gate with one input connected to OE\_n from the device, the other input connected to VPO from the device, and the output connected to USB\_P3\_6 (VPO) of the processor.

---

**5.68 Errata (FEr#68)**

**Type:** Functional Errata

**Relevant for:** PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** ML-977, MLV-1684

**Description:** USBH: USB host fails with system bus = 104 MHz or 208 MHz.

**Problem:** USB host system bus race condition can happen at product points with 104 MHz or 208 MHz on the system bus.

**Implication:** The USB host controller can hang when running at 104 MHz on the system bus. This hang can also be seen on the 208 MHz system bus product point.

**Workaround:** When using the USB host controller, do not use product points with system bus frequency of 104 MHz. When using the 624 MHz core (VCC\_APPS=1.375 V) and 208 MHz system product point, tighten the voltage tolerance on the Vcc\_Apps supply to +/- 5%.

---

**5.69 Errata (FEr#69)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-4821

**Description:** SSP: EOR is not set when FIFO Packed mode is used.

**Problem:** The SSP is not setting the EOR bit when Packed mode is enabled with DMA handling the trailing bytes. EOR is set with Packed mode disabled.

**Implication:**

**Workaround:** Use the processor for removal of trailing bytes and not DMA.

---

**5.70 Errata (FEr#70)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-6262

**Description:** SSP: SSP not functional when entering and exiting S0/D0CS/C0 prior to enabling SSP.

**Problem:** SSP clocks unstable when entering and exiting S0/D0CS/C0.

**Implication:** Clock instability causes data corruption.

**Workaround:** Before switching between S0/D0/C0 to S0/D0CS/C0 and S0/D0CS/C0 to S0/D0/C0, follow this procedure:

1. Clear all SSP registers.
2. Enable SSP by setting SSE bit.
3. Disable SSP by clearing SSE bit.
4. Enter S0/D0CS/C0.
5. Update SSP registers.
6. Enable SSP by setting SSE bit.
7. SSP activity begins.
8. Repeat the above sequence as well for exiting S0/D0CS/C0.

---

**5.71 Errata (FEr#71)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-3749

**Description:** UART: When DLL and DLH are programmed at the same time, UART takes in only the first one.

**Problem:** Two registers (DLL and DLH) are used to program the baud rate. If both are programmed at the same time, only the first register programmed affects the baud rate. The second register settings do not take affect unless another register write is made to program the baud rate.

**Implication:** Incorrect baud-rate behavior when setting DLL and DLH with back-to-back instructions.

**Workaround:** Write one register, then read it to add delay, then write the other.

---

**5.72 Errata (FEr#72)**

**Type:** Functional Errata

**Relevant for:** PXA32x - All, PXA30x - All

**Fixed in:** No Fix

**Errata BTS#:** MP-5802

**Description:** UART: TX interrupt can be missed when running full duplex

**Problem:** The TX interrupt can be missed due to the state machine getting locked into an intermediate state when a higher priority interrupt de-asserts just before the IIR register is read.

**Implication:** Transmits could stall if this situation occurs.

**Workaround:** If any interrupt occurs when running full duplex, check LSR[TDRQ] for status on the Transmit FIFO. If TDRQ is set, the FIFO is half or more empty and data needs to be written to it. After the write to the Transmit FIFO, the state machine operates normally. DMA mode is not affected by this erratum.



---

5.73 Errata (FEr#73)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-4018  
**Description:** CIR: Wrong symbols sent on second transmission after boot.  
**Problem:** The second and subsequent transmissions are corrupted when sending multiple transmissions.  
**Implication:** Incorrect commands are sent out on the CIR interface.  
**Workaround:** After receiving each EOT interrupt, perform a software reset of the CIR interface.

---

5.74 Errata (FEr#74)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All, PXA30x - All, PXA31x - All  
**Fixed in:** No Fix  
**Errata BTS#:** MP-6163  
**Description:** I2C: Bus Busy bit only changes on state transitions.  
**Problem:** ISR[BB] is only set on valid bus activity on the I<sup>2</sup>C bus.  
**Implication:** If an external master starts a transaction before the I2C peripheral is out of reset and configured, the I<sup>2</sup>C peripheral does not properly detect that the I<sup>2</sup>C bus is in use since it did not detect a START transition.  
**Workaround:** ISR[BB] bit should be set immediately when detecting transition on the bus (SCL and/or SDA).

---

5.75 Errata (FEr#75)

**Type:** Functional Errata  
**Relevant for:** PXA32x - All  
**Fixed in:** No Fix - PXA30x - All, PXA31x-All  
**Errata BTS#:** MP-6161  
**Description:** I2C: Enabling I<sup>2</sup>C unit drives SCL low.  
**Problem:** Enabling the I<sup>2</sup>C unit by setting ICR[IUE] drives SCL low.  
**Implication:** If the I<sup>2</sup>C unit is enabled in the middle of another master transaction, that transaction can become corrupted.  
**Workaround:** None

---

5.76 Errata (FEr#76)

**Type:** Functional Errata  
**Relevant for:** PXA32x-B2, PXA31x-A2, PXA30x-All  
**Fixed in:** PXA32x - C0, PXA31x - B1, PXA30x - No Fix  
**Errata BTS#:** MLV-2026  
**Description:** CORE: Random system hangs may occur when exiting S0/D0CS/C1  
**Problem:** When exiting S0/D0CS/C1 (core idle), the IDLE mode exit indicator from the Application Subsystem Core is not captured correctly in the clocks module in some cases due to synchronization across different clock domains. This causes the clocks module logic to enter an incorrect state prohibiting any further power mode changes, frequency changes, or GPIO resets.  
**Implication:** System hangs may occur when exiting S0/D0CS/C1.  
**Workaround:** Do not use S0/D0CS/C1. Software can be used as an idle replacement. The latest Marvell Board Support Packages (BSP) contain a software idler than can be used to replace S0/DOCS/C1.

---



5.77 **Errata (FEr#77)**

**Type:** Functional Errata

**Relevant for:** PXA31x-A2

**Fixed in:** No Fix

**Errata BTS#:** MLV-2166

**Description:** LCD: VGA Input and Output FIFO under-runs can occur while running in S0/D0CS/C0.

**Problem:** When using a VGA display with the DDR SDRAM clock running at 30 MHz (ACCR[DDR\_D0CS] = 1), under-runs can occur when non-LCD accesses occur to the DDR SDRAM.

**Implication:** Under-runs will occur on the VGA display when other DDR SDRAM accesses occur while operating in S0/D0CS/C0.

**Workaround:** When an interrupt occurs for a process other than the LCD Controller while running in S0/D0CS/C0 software has two options to avoid under-runs.

1. Immediately transition to an operating point with the DDR SDRAM SCLK running at 130 MHz
2. Store enough code inside the internal SRAM to handle the non-LCD processes without having to access DDR SDRAM.

---

5.78 **Errata (FEr#78)**

**Type:** Functional Errata

**Relevant for:** PXA32x-All, PXA31x-All, PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** MLV-2203

**Description:** CI: QCI will capture one line of invalid data

**Problem:** When the QCI is in any master mode, YCbCr or RGB and CICR3[BFW] is configured to 0x0, the QCI may capture one line of invalid data. This does not include the JPEG modes of operation as supported in the PXA31x. This will only occur if a HSYNC occurs after software enables the CICR0[ENB] but before VSYNC is asserted and HSYNC does not assert at the same time as VSYNC. This is typically the case if the sensor is in a free running mode with the CLK and both VSYNC and HSYNC toggling but the QCI is disabled.

**Implication:** If software enables the QCI by setting the CICR0[ENB] bit in the middle of a frame, the QCI will capture one line of invalid data. This invalid line will always be the line of data that is presented to the QCI when VSYNC is asserted at the start of the next frame. This invalid line will either be sent for preview (typically to the LCD overlay 2) or sent to a storage buffer and will show as a corrupt line of data. Once the QCI has captured this invalid line of data, every subsequent frame will also have an invalid line of data.

**Workaround:** There are four possible software workarounds to avoid this errata:

1. Configure the QCI CICR3[BFW] register to a non zero value.
2. Do not use a free running sensor configuration. Software must ensure that the QCI interface is enabled prior to a frame start.
3. Enable the QCI (CICR0[ENB] = 0b1) during the vertical blanking period:
  - a. Configure VSYNC as a GPIO and set an interrupt for a rising edge (this may be falling depending upon the sensor configuration)
  - b. In this ISR, reconfigure the GPIO back to VSYNC and set the ENB bit to start capture
  - c. This will ensure that the data capture will occur at the start of a new frame
4. If BFW=0x0 must be used then the VSYNC and HSYNC signals must be asserted at the same, on the same clock edge. If HSYNC is delayed by one pixel clock then the first line will be shifted over by one pixel. Both SYNC signals must assert on the same clock edge.



---

**5.79 Errata (FEr#79)**

**Type:** Functional Errata

**Relevant for:** PXA32x-All, PXA31x-All, PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** MP-6441

**Description:** The I2C Unit Not Busy bit (ISR[UB]) remains set after Master Abort

**Problem:** When the I2C is in master transmit mode and a master abort (ICR[MA]) is issued during the address phase the I2C controller will hang.

**Implication:** If software issues the master abort command (ICR[MA]) during the address phase of an I2C transfer the I2C controller will hang.

**Workaround:** Ensure software does not issue a master abort command during the address phase of an I2C transfer.

---

**5.80 Errata (FEr#80)**

**Type:** Functional Errata

**Relevant for:** PXA31x - A2, B1, PXA30x - A1.A

**Fixed in:** No Fix

**Errata BTS#:** COMP-518

**Description:** ROM: Boot ROM clears the OS Timer Count Register 0 (OSCR0) register while handling resets.

**Problem:** When a reset occurs the Boot ROM will clear the OSCR0 register.

**Implication:** Software that depends on the OSCR0 register value will not work properly.

**Workaround:** If continuity of OSCR0 needs to be preserved, software must save the OSCR0 value before entering sleep, and then restore OSCR0 upon wake

---

**5.81 Errata (FEr#81)**

**Type:** Functional Errata

**Relevant for:** PXA32x-All, PXA31x-All, PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** MP-6451, MLV-2221, ML-1187

**Description:** OS Timer interrupts 4 – 11 are missed when an OS Timer Status Register (OSSR) Write occurs at the same time as a match-event interrupt occurs.

**Problem:** OS Timers 4 – 11 share a common interrupt request (IP[7]) to the interrupt controller that is used to indicate a match event from any of the 4 – 11 timers. When software is writing to the OSSR to clear the status bits at the same time a new timer match interrupt occurs, the OSSR status bit for the new match event is set to indicate a new timer match event has occurred, but the interrupt request for the new OS Timer match event does not get sent to the interrupt controller. For software using a common Interrupt Service Routine (ISR) for all 4 – 11 timers, a new match event interrupt request will not be sent to the interrupt controller while the OSSR register is being written to clear the status bits for another timer match event.

**Implication:** The OST\_4\_11 bits in the Interrupt Controller FIQ Pending Register (ICFP) or Interrupt Controller IRQ Pending Register (ICIP) will not be set to indicate an interrupt for OS Timers 4-11 has occurred. The OS Timer match event that occurred during the OSSR write will not be serviced by the interrupt controller.

**Workaround:** The ISR software for OS Timers 4-11 must check the value of the OSSR before and after the Write to the OSSR and ensure that no other match events occurred while the OSSR Write occurred. When the OSSR Read after the OSSR Write shows a new match occurred, software must handle that OS Timer interrupt prior to exiting the ISR. Software outside of the ISR that writes to the OSSR register also must ensure that no match events occurred while the OSSR write occurred. If an OS match event occurs during this OSSR write software must execute the interrupt handler for that timer to avoid it from being missed.

---

5.82 **Errata (FEr#82)**

**Type:** Functional Errata

**Relevant for:** PXA32x-All, PXA31x-All, PXA30x-All

**Fixed in:** No Fix

**Errata BTS#:** ML-1180

**Description:** SERVICES: EXT\_WAKEUP<1:0> wakes up on both rising and falling edges regardless of PWER[WEx[1:0]] settings.

**Problem:** The Wakeup Enable on Rising Edge (WER[1:0]) and Wakeup Enable on Falling Edge (WEF[1:0]) bits in the Power Manager Wake-up Enable Register (PWER) have no effect on limiting the wakeup source for EXT\_WAKEUP<1:0> from S2/D3/C4 to rising or falling edge only. These bits are valid only for wake-ups from S3/D4/C4.

**Implication:** Designs that use EXT\_WAKEUP<1:0> to place the processor in S2/D3/C4 will wake up when the pin is released because the wakeup is not limited to one edge.

**Workaround:** None. For designs that must use EXT\_WAKEUP<1:0> to place the processor in S2/D3/C4, Marvell recommends turning off the LCD backlight when the pin is asserted to simulate the processor being in S2/D3/C4 mode, and waiting for the pin to de-assert before software actually places the processor in S2/D3/C4.



## 6. Specification Clarifications Summary

Table 6: Summary of Specification Clarifications

Number	Description	Document	Relevant Revision	Revision Fixed
7.1 Changes(SCR#1)	An extra, unused EMPI clock can be left on and consume extra power.	Marvell® PXA32x processor	PXA32x - All	No Fix
7.2 Changes(SCR#2)	Meeting NAND tADL timing requirements.	PXA3xx Processors	NA	NA
7.3 Changes(SCR#3)	The PXA301 MCP package does not include a unique identification number (UUID).	PXA301	Multi-Chip Packages	No Fix

## 7. Detailed Descriptions for Specification Clarifications

---

### 7.1 Changes(ScR#1)

**Type:** Specification Clarification  
**Relevant for:** Marvell® PXA32x processor  
**Revision:** PXA32x - All  
**Fixed In:** No Fix  
**Errata BTS#:** MP-5454  
**Description:** An extra, unused EMPI clock can be left on and consume extra power.

#### **Changes:**

The EMPI SCLK is a clock that the SMC uses on the EMPI bus. Split Bus mode where the SMC shares the EMPI bus with the DMC is no longer supported, so this signal is no longer used. Use the following software procedure to disable this clock:

- Set the EMPI\_SCLK Pad Control Register (0x40E1\_00CC) to 1.
- Clear the PAD\_SCLK (0x4810\_012C) to 0.
- Set the RCOMP[UPDATE] (0x4810\_0100) to 1.

---

### 7.2 Changes(ScR#2)

**Type:** Specification Clarification  
**Relevant for:** PXA3xx Processors  
**Revision:** NA  
**Fixed In:** NA  
**Errata BTS#:** ML-6381  
**Description:** Meeting NAND tADL timing requirements.

**Reason:** The tADL NAND timing requirement must met by using multiple PXA3xx NAND Flash Controller (NFC) timing registers. The tADL time is a requirement that exists during a program operation between the de-assertion of the nWE signal during the last address cycle, to the initial nWE de-assertion on the first word/byte of data during the Write cycle. Without meeting this timing requirement there is a possibility that at least the first word/byte can be corrupted going into the NAND device, which could lead to data corruption and bad-block errors. This tADL timing requirement applies to most raw NAND devices.

To meet this timing, use the combination of NDTR0CS0[tWP] (nWE assertion time) and NDTR0CS0[tCH] (ALE hold time). To minimize overall system performance, Marvell recommends using the smallest tWP time that meets the normal Write cycle times for the NAND device and increase the tCH value, as shown in the example below.

- NAND Timing Parameters
  - tWC = 45 ns
  - tWH = 15 ns
  - tWP = 25 ns
  - tADL = 100 ns
- PXA3xx Timing Parameters
  - NFC Clock period 9.6 ns (104 MHz)
  - 3 NFC Clock delay for internal processing (28.85 ns)
  - NDTR0CS0[tWP] = 2
  - nWE assertion time is tWP+1 = 28.85 ns
  - NDTR0CS0[tCH] = 4



- ALE hold time is  $t_{CH} + 1 = 48.07$  ns ( $t_{CH}$  maximum is 7)
  - Total time from nWE de-assertion (address) to nWE de-assertion (data) = 105.77 ns
  - Total time from nWE de-assertion (address) to nWE de-assertion (data) = 102.55 ns
- 

### **7.3 Changes(SCr#3)**

**Type:** Specification Clarification

**Relevant for:** PXA301

**Revision:** Multi-Chip Packages

**Fixed In:** No Fix

**Errata BTS#:** ML-1162

**Description:** The PXA301 MCP package does not include a unique identification number (UUID).

#### **Reason:**

For designs that require a unique identification number, the PXA301 MCP package does not support this feature. External design considerations must be put in place to accommodate this requirement. Marvell recommends using an external device on the board that supports the UUID.

-

## 8. Specification Changes Summary

**Table 7: Summary of Specification Changes**

Number	Description	Processor	Relevant Revision
9.1 Changes(SCr#1)	The Resistive Compensation (RCOMP) formula has changed on the PXA310 processor and is different than the PXA30x processor.	PXA31x Processor	A2, B1
9.2 Changes(SCr#2)	Boot ROM has too low value for NAND tR timing register in the NDTR1CS0	PXA30x - A1, PXA31x-A1	PXA30x - A1, PXA31x-A1
9.2 Changes(SCr#2)	Three new operating points have been added to the PXA31x processors A2 stepping.	PXA31x Processor	A2, B1
9.3 Changes(SCr#3)	Three external DMA request signals (DREQ<3:1>) for the Static Memory Controller have been added.	PXA31x Processor	B1
9.4 Changes(SCr#4)	New CPU and JTAG IDs, and Processor Revision numbers have been added for the PXA31x-B1 and PXA32x-C0 stepping processors.	PXA32x and PXA31x Processors	PXA32x-C0 , PXA31x-B1
9.5 Changes(SCr#5)	An option has been added for running the Dynamic Memory Controller at 60 MHz instead of the default 30 MHz.	PXA32x Processors	C0
9.6 Changes(SCr#6)	New register added to control arbitration between the NFC and SMC when disabling the NAND clock during NFC register writes.	PXA31x	B1
9.7 Changes(SCr#7)	GPIO13 output functionality has been added to the DF_ALE_nWE1 and DF_ALE_nWE signals	PXA32x and PXA31x Processors	PXA32x-C0, PXA31x-B1
9.8 Changes(SCr#8)	LCD data lines increased to support 24 bits (L_DD<23:0>)	PXA32x and PXA31x Processors	PXA32x-C0, PXA31x-B1
9.9 Changes(SCr#9)	The PXA32x-C0 boot ROM has been upgraded to include a reset command being issued to the NAND device when a power on reset occurs.	PXA32x Processors	C0
9.10 Changes(SCr#10)	Support for 156 MHz DDR SCLK has been added to these processors	PXA32x and PXA31x Processors	PXA32x-C0, PXA31x-B1
Relevant for:)	The VCC_APPS and VCC_SRAM voltage levels for each operating point and power mode have decreased to improve power consumption.	PXA32x and PXA31x Processors	PXA32x-C0, PXA31x-B1



## 9. Detailed Descriptions for Specification Changes

### 9.1 Changes(SCr#1)

**Type:** Specification Change

**Relevant for:** PXA31x Processor

**Revision:** A2, B1

**Errata BTS#:** MLV-1825

**Description:** The Resistive Compensation (RCOMP) formula has changed on the PXA310 processor and is different than the PXA30x processor.

#### Changes:

Software must use the updated formulas to ensure proper DDR SDRAM operation.

#### PXA30x processor formula:

$PSLEW = -2.96 - 0.0435(PCODE) + 0.348(NCODE)$

$NSLEW = 2.88 + 0.250(PCODE) - 0.125(NCODE)$

#### PXA31x processor formula:

$PSLEW = 3.9114 - 0.1172(PCODE) + 0.1964(NCODE)$

$NSLEW = -9.4340 + 0.3564(PCODE) + 0.1906(NCODE)$

### 9.2 Changes(SCr#2)

**Type:** Specification Change

**Relevant for:** PXA31x Processor

**Revision:** A2, B1

**Errata BTS#:** MLV-2231

**Description:** Three new operating points have been added to the PXA31x processors A2 stepping.

**Changes:** A new PXA31x processor SKU is being offered with two new 806 MHz operating points as defined in [Table 8](#). In addition, a 624 MHz operating point with system bus running at 312 MHz has also been added. The voltage levels for these new operating points are defined in [Table 9](#).



**Table 8: PXA31x Core PLL, Turbo and Run Mode Output Frequencies**

XL	XN	Frequency (MHz)									
		Run (ACCR[XL])	Turbo (ACCR[XNI])	Switch (ACCR[XL])	System Bus (ACCR[HSS])	LCD (ACCR[HSS])	Internal SRAM Controller (ACCR[SFLFS])	DDR Controller SDRAM Clock (ACCR[DMCFS])	Static Memory Controller (ACCR[SMCFS])	Data Flash Controller not programmable	Video Accelerator Unit (ACCR[VAUF])
Ring Oscillator <sup>1</sup>		60	—	60	60	60	60	30	15	30	60
8 <sup>2</sup>	1	104 (0x01)	— (0x01)	104 (0x01)	104 (0x00)	104 (0x00)	104 (0x00)	26 (0x00)	78 (0x00)	19.5	104 (0x00)
8	1	104 (0x08)	— (0x01)	104 (0x08)	104 (0x00)	104 (0x00)	104 (0x00)	130 (0x03)	78 (0x00)	156	78 (0x03)
16	1	208 (0x10)	— (0x01)	208 (0x10)	104 (0x00)	104 (0x00)	156 (0x01)	130 (0x03)	104 (0x02)	156	78 (0x03)
16	2	208 (0x10)	416 (0x02)	208 (0x10)	156 (0x01)	156 (0x01)	208 (0x02)	130 (0x03)	104 (0x02)	156	104 (0x00)
24	2	312 (0x18)	624 (0x02)	312 (0x18)	208 (0x02)	208 (0x02)	312 (0x03)	130 (0x03)	208 (0x05)	156	156 (0x01)
24	2	312 (0x18)	624 (0x02)	312 (0x18)	312 (0x03)	312 (0x03)	312 (0x03)	130 (0x03)	208 (0x05)	156	156 (0x01)
31	2	403 (0x1F)	806 (0x02)	403 (0x1F)	208 (0x02)	208 (0x02)	312 (0x03)	130 (0x03)	208 (0x05)	156	156 (0x01)
31	2	403 (0x1F)	806 (0x02)	403 (0x1F)	312 (0x03)	312 (0x03)	312 (0x03)	130 (0x03)	208 (0x05)	156	156 (0x01)
<p><b>NOTE:</b></p> <ol style="list-style-type: none"> <li>Frequencies shown in this row are ideal-nominal and are based upon the ring oscillator, which has a <math>\pm 2\%</math> tolerance; actual frequencies may deviate from values provided.</li> <li>XL = 8, XN = 1 (DDR = 26 MHz) is the reset state used for hardware boot-up frequency only and must not be used for normal operation.</li> </ol>											



**Table 9: Voltage, Temperature, and Frequency Electrical Specifications**

Symbol	Description	Min	Typical	Max	Units	Notes
<b>VCC_APPS Voltage at Frequency Ranges (Turbo/Run/Switch/System Bus), (Power Mode (Sx/Dx/Cx))</b>						
Vccapps_3	Voltage applied on VCC_APPS at 624/312/312/208	1.31	1.375	1.475	V	2
Vccapps_3	Voltage applied on VCC_APPS at 624/312/312/312	1.42	1.45	1.475	V	2
Vccapps_4	Voltage applied on VCC_APPS in S0/D2/C2, S0/D1/C2 or at 806/403/403/208	1.33	1.40	1.50	V	2
Vccapps_4	Voltage applied on VCC_APPS at 806/403/403/312	1.42	1.45	1.50	V	2
Tpwrramp	Ramp Rate	2.00	10.00	12.00	mV/μs	—
<b>VCC_SRAM Voltage at Frequency Range (Turbo/Run/Switch/System Bus), (Power Mode (Sx/Dx/Cx) @ SRAM frequency)</b>						
Vccsram_3	Voltage applied on VCC_SRAM at 624/312/312/208	1.31	1.375	1.475	V	2, 5
Vccsram_3	Voltage applied on VCC_SRAM at 624/312/312/312	1.335	1.375	1.475	V	2, 5
Vccsram_4	Voltage applied on VCC_SRAM in S2/D3/C4 <sup>4</sup> , S0/D2/C2, S0/D1/C2, or 806/403/403/208	1.33	1.40	1.5	V	2, 5
Vccsram_4	Voltage applied on VCC_SRAM in or 806/403/403/312	1.355	1.40	1.5	V	2, 5
Tpwrramp	Ramp Rate	2.00	10.00	12.00	mV/μs	6

**Table 9: Voltage, Temperature, and Frequency Electrical Specifications (Continued)**

Symbol	Description	Min	Typical	Max	Units	Notes
<b>NOTE:</b>						
<ol style="list-style-type: none"> <li>1. System design must ensure that the device case temperature is maintained within the specified limits. In some system applications it may be necessary to use external thermal management (for example, a package-mounted heat spreader) or configure the device to limit power consumption and maintain acceptable case temperatures.</li> <li>2. The voltage ranges specified for VCC_APPS and VCC_SRAM are the targeted voltage ranges for the product. These ranges may extend or narrow depending on actual product performance and product skews. Marvell recommends that extended voltage and current capabilities be designed into the power management IC to accommodate future changes to this specification without requiring changes to the power management IC.</li> <li>3. VCC_MVT requires the capability to increase from the normal operating voltage of 1.8 V to 1.9 V during certain times. This increased voltage is required under certain conditions, not during normal operation. When VCC_MVT is raised to 1.9 V, it is operating in "boost mode". Boost mode is only used during factory programming. If VCC_PLL, VCC_OSC13M and VCC_BG are supplied by the same PMIC supply, which is the method Marvell recommends, these other voltages also operate at 1.9 V. Maximum current capabilities and voltage tolerances are identical in boost mode and normal operation.</li> <li>4. This option allows one or more 128 Kbyte SRAM banks to retain state during S2/D3/C4 mode.</li> <li>5. Reset voltage for VCC_APPS and VCC_SRAM is 1.4 V and the startup frequency is 104/104/104/104 MHz.</li> <li>6. Min ramp rate = (Maximum voltage transition) / (LPM_DEL - ((Power I2C command execution time))</li> <li>7. PXA32x Only</li> </ol>						

**9.3 Changes(SCr#3)**

**Type:** Specification Change

**Relevant for:** PXA31x Processor

**Revision:** B1

**Errata BTS#:** MLV-1273

**Description:** Three external DMA request signals (DREQ<3:1>) for the Static Memory Controller have been added.

**Changes:** Refer to [Table 10](#) for details on the DREQ<3:1> signals on GPIO<2:0> alternate function 6.

**Table 10: Static Memory Controller External Signal Descriptions**

Ball Name	Signal Name	Direction	Description
GPIO0	DREQ1	Input	Static Memory Controller DMA request line (PXA31x processor only) The external SMC chip asserts the DREQ signal when a DMA transfer is required. The DREQ signal must remain asserted for four DF_SCLK cycles to allow the DMA Controller to recognize a low-to-high transition.
GPIO1	DREQ2	Input	Static Memory Controller DMA request line (PXA31x processor only) The external SMC chip asserts the DREQ signal when a DMA transfer is required. The DREQ signal must remain asserted for four DF_SCLK cycles to allow the DMA Controller to recognize a low-to-high transition.



**Table 10: Static Memory Controller External Signal Descriptions (Continued)**

Ball Name	Signal Name	Direction	Description
GPIO2	DREQ3	Input	Static Memory Controller DMA request line (PXA31x processor only) The external SMC chip asserts the DREQ signal when a DMA transfer is required. The DREQ signal must remain asserted for four DF_SCLK cycles to allow the DMA Controller to recognize a low-to-high transition.

**9.4 Changes(ScR#4)**

**Type:** Specification Change  
**Relevant for:** PXA32x and PXA31x Processors  
**Revision:** PXA32x-C0 , PXA31x-B1  
**Errata BTS#:** MLV-2264  
**Description:** New CPU and JTAG IDs, and Processor Revision numbers have been added for the PXA31x-B1 and PXA32x-C0 stepping processors.  
**Changes:** Refer to [Table 11](#) and [Table 12](#) for the updated register descriptions

**Table 11: Processor ID Register**

		Coprorocessor 15 Register 0 opcode_2 = 0																Processor ID Register																Processor ID															
Bit		31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0																
Reset		Vendor								Arch Version								Core G				Core R				Prod ID				Prod R																			
		0	1	1	0	1	0	0	1	0	0	0	0	0	1	0	1	0	1	1	†	†	†	†	†	†	†	†	†	†	†	†	†	†															
		Bits				Name				Access				Description																																			
		3:0				Prod R				Read-Only				Processor Revision Processor stepping: 0b0001 = A1 0b0010 = A2 0b0011 = B1 0b0110 = B2 0b0111 = C0																																			

**Table 12: Coprocessor: New CPU ID and JTAG ID Values**

Stepping	CPU ID	JTAG ID
PXA30x-A0	0x6905_6880	0x0E64_8013
PXA-30x-A1	0x6905_6881	0x1E64_8013
PXA31x-A0	0x6905_6890	0x0E64_9013
PXA31x-A1	0x6905_6891	0x1E64_9013

**Table 12: Coprocessor: New CPU ID and JTAG ID Values (Continued)**

Stepping	CPU ID	JTAG ID
PXA31x-A2	0x6905_6892	0x2E64_9013
PXA31x-B1	0x6905_6893	0x3E64_9013
PXA32x-B1	0x6905_6825	0x5E64_2013
PXA32x-B2	0x6905_6826	0x6E64_2013
PXA32x-C0	0x6905_6827	0x7E64_2013

---

**9.5 Changes(SCR#5)**

**Type:** Specification Change

**Relevant for:** PXA32x Processors

**Revision:** C0

**Errata BTS#:** MLV-2077

**Description:** An option has been added for running the Dynamic Memory Controller at 60 MHz instead of the default 30 MHz.

**Changes:** Refer to [Table 13](#) for the DDR\_D0CS bit definition that allows software to change the DMC frequency in S0/D0CS/C0.



**Changes:** Refer to [Table 14](#) for the new Arbitration Control (NDCR[ARB\_CNTL]) register definition.

**Table 14: NDCR Bit Definitions**

Physical Address 0x4310_0000		NDCR																			NAND Flash Controller																		
User Settings	Bit	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0						
PXA32x and PXA30x Only		SPARE_EN	ECC_EN	DMA_EN	ND_RUN	DWIDTH_C	DWIDTH_M	PAGE_SZ		NCSX	Reserved		CLR_PG_CNT	Reserved	RD_ID_CNT			RA_START	PG_PER_BLK	Reserved	ND_ARB_EN	RDYM	CS0_PAGEDM	CS1_PAGEDM	CS0_CMDDM	CS1_CMDDM	CS0_BBDM	CS1_BBDM	DBERRM	SBERRM	WRDREQM	RDDREQM	WRCMDREQM						
PXA31x Only		SPARE_EN	ECC_EN	DMA_EN	ND_RUN	DWIDTH_C	DWIDTH_M	PAGE_SZ		NCSX	Reserved		CLR_PG_CNT	ARB_CNTL	RD_ID_CNT			RA_START	PG_PER_BLK	Reserved	ND_ARB_EN	RDYM	CS0_PAGEDM	CS1_PAGEDM	CS0_CMDDM	CS1_CMDDM	CS0_BBDM	CS1_BBDM	DBERRM	SBERRM	WRDREQM	RDDREQM	WRCMDREQM						
Reset		0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	?	0	1	1	1	1	1	1	1	1	1	1	1	1						
		Bits		Access		Name		Description																															
	19			R/W		ARB_CNTL		Arbitration Control (PXA31x Only) The Data Flash Interface (DFI) bus-arbiter control (ARB_CNTL) bit controls the ownership of DFI bus. The DFI bus is shared between the Static Memory Controller (SMC) and the NFC to transfer data to/from external memory devices. Software must set this bit before disabling the NFC clock (DOCKEN_A[CKEN4]) to ensure SMC accesses will occur while the clock is disabled. . 0 = Normal DFI arbitration between NFC and SMC 1 = DFI bus arbitration granted to the SMC  Procedures for using ARB_CNTL when programming NFC registers 1. Ensure NFC is idle (NDCR[ND_RUN] = 0b0) 2. Set ARB_CNTL to 0b1 3. Verify ARB_CNTL is set to 0b1 4. Disable NFC clock by clearing DOCKEN_A[CKEN4] to 0b0 5. Program NFC registers for next access 6. Enable NFC clock by setting DOCKEN_A[CKEN4] to 0b1 7. Clear ARB_CNTL to 0b0																															
				—		—		reserved (PXA32x and PXA30x Only)																															



**9.7 Changes(ScR#7)**

**Type:** Specification Change  
**Relevant for:** PXA32x and PXA31x Processors  
**Revision:** PXA32x-C0, PXA31x-B1  
**Errata BTS#:** MLV-1960  
**Description:** GPIO13 output functionality has been added to the DF\_ALE\_nWE1 and DF\_ALE\_nWE signals  
**Changes:** Refer to [Table 15](#) and [Table 16](#) for alternate function definitions for GPIO13 on these pins.

**Table 15: PXA32x DF\_ALE\_nWE1 alternate function definitions**

Pin Name	Primary Function at Reset (Alt FN0)	Alt. FN 1	Alt. FN 2	Alt. FN 3	Alt. FN 4	Alt. FN 5	Alt. FN 6	Alt. FN 7
DF_ALE_nWE1	GPIO13_2	DF_ALE_nWE						

**Table 16: PXA31x DF\_ALE\_nWE alternate function definitions**

Pin Name	Primary Function at Reset (Alt FN0)	Alt. FN 1	Alt. FN 2	Alt. FN 3	Alt. FN 4	Alt. FN 5	Alt. FN 6	Alt. FN 7
DF_ALE_nWE	GPIO13_2	DF_ALE_nWE						

**9.8 Changes(ScR#8)**

**Type:** Specification Change  
**Relevant for:** PXA32x and PXA31x Processors  
**Revision:** PXA32x-C0, PXA31x-B1  
**Errata BTS#:** MLV-2240, MP-6470  
**Description:** LCD data lines increased to support 24 bits (L\_DD<23:0>)  
**Changes:** Refer to [Table 17](#) and [Table 18](#) for pin assignments for the new LCD data signals L\_DD<23:18>

**Table 17: PXA32x Processor L\_DD<23:18> pin assignments**

Pin Name	Alternate Function	LCD Data signal
GPIO83	6	L_DD<18>
GPIO88	6	L_DD<19>
GPIO105	6	L_DD<20>



**Table 17: PXA32x Processor L\_DD<23:18> pin assignments (Continued)**

Pin Name	Alternate Function	LCD Data signal
GPIO106	7	L_DD<21>
GPIO107	6	L_DD<22>
GPIO108	6	L_DD<23>

**Table 18: PXA31x Processor L\_DD<23:18> pin assignments**

Pin Name	Alternate Function	LCD Data signal
GPIO53	7	L_DD<18>
GPIO104	7	L_DD<19>
GPIO106	7	L_DD<20>
GPIO107	7	L_DD<21>
GPIO108	7	L_DD<22>
GPIO127	6	L_DD<23>

---

**9.9 Changes(SCr#9)**

**Type:** Specification Change

**Relevant for:** PXA32x Processors

**Revision:** C0

**Errata BTS#:** MP-6480

**Description:** The PXA32x-C0 boot ROM has been upgraded to include a reset command being issued to the NAND device when a power on reset occurs.

**Changes:** ONFI compliant devices that require a reset command can now be supported.

---

**9.10 Changes(SCr#10)**

**Type:** Specification Change

**Relevant for:** PXA32x and PXA31x Processors

**Revision:** PXA32x-C0, PXA31x-B1

**Errata BTS#:** MLV-2213

**Description:** Support for 156 MHz DDR SCLK has been added to these processors

**Changes:** Refer to [Table 19](#) for the correct ACCR[DMCFS] bit definitions that allows the DDR SCLK to operate at 156 MHz.. Refer to [Table 20](#) for supported PXA32x processor operating points with the 156 MHz DDR SCLK and [Table 21](#) for the PXA31x operating points. The operating points in [Table 20](#) and [Table 21](#) cannot be used with operating points with a 130 MHz DDR SCLK.



**Table 20: PXA32x Core PLL, Turbo and Run Mode Output Frequencies (ACCR[DMCFS] = 156 MHz)**

XL	XN	Frequency (MHz)								
		Run (ACCR[XL])	Turbo (ACCR[XN])	Switch (ACCR[XL])	System Bus (ACCR[HSS])	LCD (ACCR[HSS])	Internal SRAM Controller (ACCR[SFLFS])	DDR Controller SDRAM Clock (ACCR[DMCFS])	Static Memory Controller (ACCR[SMCFS])	Data Flash Controller not programmable
Ring Oscillator <sup>1</sup>		60	—	60	60	60	60	30	15	30
8 <sup>2</sup>	1	104 (0x01)	— (0x01)	104 (0x01)	104 (0x00)	104 (0x00)	104 (0x00)	26 (0x00)	78 (0x00)	19.5
8	1	104 (0x08)	— (0x01)	104 (0x08)	104 (0x00)	104 (0x00)	104 (0x00)	156 (0x01)	78 (0x00)	156
16	1	208 (0x10)	— (0x01)	208 (0x10)	104 (0x00)	104 (0x00)	156 (0x01)	156 (0x01)	104 (0x02)	156
16	2	208 (0x10)	416 (0x02)	208 (0x10)	156 (0x01)	156 (0x01)	208 (0x02)	156 (0x01)	104 (0x02)	156
24	2	312 (0x18)	624 (0x02)	312 (0x18)	208 (0x02)	208 (0x02)	312 (0x03)	156 (0x01)	208 (0x05)	156
31	2	403 (0x1F)	806 (0x02)	403 (0x1F)	208 (0x02)	208 (0x02)	312 (0x03)	156 (0x01)	208 (0x05)	156
<p><b>NOTE:</b></p> <ol style="list-style-type: none"> <li>Frequencies shown in this row are ideal-nominal and are based upon the ring oscillator, which has a ±2% tolerance; actual frequencies may deviate from values provided.</li> <li>XL = 8, XN = 1 (DDR = 26 MHz) is the reset state used for hardware boot-up frequency only and must not be used for normal operation.</li> </ol>										

Table 21: PXA31x Core PLL, Turbo and Run Mode Output Frequencies (ACCR[DMCFS] = 156 MHz)

XL	XN	Frequency (MHz)									
		Run (ACCR[XL])	Turbo (ACCR[XN])	Switch (ACCR[XL])	System Bus (ACCR[HSS])	LCD (ACCR[HSS])	Internal SRAM Controller (ACCR[SFLFS])	DDR Controller SDRAM Clock (ACCR[DMCFS])	Static Memory Controller (ACCR[SMCFS])	Data Flash Controller not programmable	Video Accelerator Unit (ACCR[VAUF])
Ring Oscillator <sup>1</sup>		60	—	60	60	60	60	30	15	30	60
8 <sup>2</sup>	1	104 (0x01)	— (0x01)	104 (0x01)	104 (0x00)	104 (0x00)	104 (0x00)	26 (0x00)	78 (0x00)	19.5	104 (0x00)
8	1	104 (0x08)	— (0x01)	104 (0x08)	104 (0x00)	104 (0x00)	104 (0x00)	156 (0x01)	78 (0x00)	156	78 (0x03)
16	1	208 (0x10)	— (0x01)	208 (0x10)	104 (0x00)	104 (0x00)	156 (0x01)	156 (0x01)	104 (0x02)	156	78 (0x03)
16	2	208 (0x10)	416 (0x02)	208 (0x10)	156 (0x01)	156 (0x01)	208 (0x02)	156 (0x01)	104 (0x02)	156	104 (0x00)
24	2	312 (0x18)	624 (0x02)	312 (0x18)	208 (0x02)	208 (0x02)	312 (0x03)	156 (0x01)	208 (0x05)	156	156 (0x01)
24	2	312 (0x18)	624 (0x02)	312 (0x18)	312 (0x03)	312 (0x03)	312 (0x03)	156 (0x01)	208 (0x05)	156	156 (0x01)
31	2	312 (0x1F)	806 (0x02)	403 (0x18)	208 (0x02)	208 (0x02)	312 (0x03)	156 (0x01)	208 (0x05)	156	156 (0x01)
31	2	312 (0x1F)	806 (0x02)	403 (0x18)	312 (0x03)	312 (0x03)	312 (0x03)	156 (0x01)	208 (0x05)	156	156 (0x01)

**NOTE:**

- Frequencies shown in this row are ideal-nominal and are based upon the ring oscillator, which has a  $\pm 2\%$  tolerance; actual frequencies may deviate from values provided.
- XL = 8, XN = 1 (DDR = 26 MHz) is the reset state used for hardware boot-up frequency only and must not be used for normal operation.

**9.11 Changes(ScR#11)**

**Type:** Specification Change

**Relevant for:** PXA32x and PXA31x Processors

**Revision:** PXA32x-C0, PXA31x-B1

**Errata BTS#:** MLV-1872

**Description:** The VCC\_APPS and VCC\_SRAM voltage levels for each operating point and power mode have decreased to improve power consumption.

**Changes:** Refer to [Table 22](#) for updated VCC\_APPS and VCC\_SRAM voltage specifications.

**Table 22: Voltage, Temperature, and Frequency Electrical Specifications**

Symbol	Description	Min	Typical	Max	Units	Notes
<b>VCC_APPS Voltage at Frequency Ranges (Turbo/Run/Switch/System Bus), (Power Mode (Sx/Dx/Cx))</b>						
Vccapps_0	Voltage applied on VCC_APPS S3/D4/C4	—	0	—	V	2
Vccapps_1	Voltage applied on VCC_APPS at (S0/D0CS/Cx), (104/104/104/104), (208/208/208/104)	0.975	1	1.1	V	2
Vccapps_2	Voltage applied on VCC_APPS at (416/208/208/156)	1.05	1.10	1.2	V	2
Vccapps_3	Voltage applied on VCC_APPS at 624/312/312/208	1.188	1.25	1.35	V	2
Vccapps_3	Voltage applied on VCC_APPS at 624/312/312/312	1.42	1.45	1.475	V	2
Vccapps_3	Voltage applied on VCC_APPS in S0/D2/C2 or S0/D1/C2	1.05	1.10	1.2	V	2
Vccapps_4	Voltage applied on VCC_APPS at 806/403/403/208	1.235	1.30	1.4	V	2
Vccapps_4	Voltage applied on VCC_APPS at 806/403/403/312	1.42	1.45	1.475	V	2
Tpwrramp	Ramp Rate	2.00	10.00	12.00	mV/μs	6
<b>VCC_SRAM Voltage at Frequency Range (Turbo/Run/Switch/System Bus), (Power Mode (Sx/Dx/Cx)) @ SRAM frequency</b>						
Vccsram_0	Voltage applied on VCC_SRAM S3/D4/C4	—	0	—	V	2
Vccsram_1	Voltage applied on VCC_SRAM at (S0/D0CS/Cx), (104/104/104/104), (208/208/208/104)	0.975	1	1.1	V	2
Vccsram_2	Voltage applied on VCC_SRAM at (416/208/208/156)	1.05	1.10	1.2	V	2
Vccsram_3	Voltage applied on VCC_SRAM at 624/312/312/208	1.188	1.25	1.35	V	2
Vccsram_3	Voltage applied on VCC_SRAM at 624/312/312/312	1.42	1.45	1.475	V	2
Vccsram_3	Voltage applied on VCC_SRAM in S0/D2/C2 or S0/D1/C2	1.05	1.10	1.2	V	2
Vccsram_4	Voltage applied on VCC_SRAM at 806/403/403/208	1.235	1.30	1.4	V	2



Table 22: Voltage, Temperature, and Frequency Electrical Specifications (Continued)

Symbol	Description	Min	Typical	Max	Units	Notes
Vccsram_4	Voltage applied on VCC_SRAM at 806/403/403/312	1.42	1.45	1.475	V	2
Tpwrramp	Ramp Rate	2.00	10.00	12.00	mV/μs	6

**NOTE:**

1. System design must ensure that the device case temperature is maintained within the specified limits. In some system applications it may be necessary to use external thermal management (for example, a package-mounted heat spreader) or configure the device to limit power consumption and maintain acceptable case temperatures.
2. The voltage ranges specified for VCC\_APPS and VCC\_SRAM are the targeted voltage ranges for the product. These ranges may extend or narrow depending on actual product performance and product skews. Marvell recommends that extended voltage and current capabilities be designed into the power management IC to accommodate future changes to this specification without requiring changes to the power management IC.
3. VCC\_MVT requires the capability to increase from the normal operating voltage of 1.8 V to 1.9 V during certain times. This increased voltage is required under certain conditions, not during normal operation. When VCC\_MVT is raised to 1.9 V, it is operating in “boost mode”. Boost mode is only used during factory programming. If VCC\_PLL, VCC\_OSC13M and VCC\_BG are supplied by the same PMIC supply, which is the method Marvell recommends, these other voltages also operate at 1.9 V. Maximum current capabilities and voltage tolerances are identical in boost mode and normal operation.
4. This option allows one or more 128 Kbyte SRAM banks to retain state during S2/D3/C4 mode.
5. Reset voltage for VCC\_APPS and VCC\_SRAM is 1.4 V and the startup frequency is 104/104/104/104 MHz.
6. Min ramp rate = (Maximum voltage transition) / (LPM\_DEL - ((Power I2C command execution time))

## 10. Documentation Changes Summary

**Table 23: Summary of Documentation Changes**

Number	Description	Document	Relevant Revision	Revision Fixed
11.1 Changes(Scr#1)	PCLK_STALL bit description missing from bit 28 of the LCD Controller Control Register 3 (LCCR3).	PXA3xx Processor Family Vol. II: Memory Controller Configuration Developers Manual	2.0	Next Revision
11.2 Changes(Scr#2)	HCOFF2 and HCOFF3 registers are missing from the DDR_HCAL register.	PXA3xx Processor Family Vol. II: Memory Controller Configuration Developers Manual	2.0	Next Revision



## 11. Detailed Descriptions for Documentation Changes

### 11.1 Changes(SCr#1)

Type: Documentation Change

Relevant for: *PXA3xx Processor Family Vol. II: Memory Controller Configuration Developers Manual*

Revision: 2.0

Fixed In: Next Revision

Errata BTS#: MP-6478

Description: PCLK\_STALL bit description missing from bit 28 of the LCD Controller Control Register 3 (LCCR3).

Changes: The LCCR3 register has been updated as shown in [Table 25](#).

Current Documentation:

Table 24: LCCR3 Bit Definitions

	Physical Address 0x4400_000C								LCCR3								LCD Controller																			
User Settings																																				
Bit	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0				
	PDFOR			BPP3	Reserved	DPC			BPP				OEP	PCP	HSP	VSP	API			ACB				PCD												
Reset	0	0	0	?	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
	Bits				Access				Name				Description																							
	28				—				—				NOTE: Reserved																							







11.2 Changes(SCR#2)

Type: Documentation Change  
 Relevant for: PXA3xx Processor Family Vol. II: Memory Controller Configuration Developers Manual  
 Revision: 2.0  
 Fixed In: Next Revision  
 Errata BTS#: MP-6479  
 Description: HCOFF2 and HCOFF3 registers are missing from the DDR\_HCAL register.  
 Changes: Refer to Table 26 for bit definitions locations for HCOFF3 and HCOFF2.

Table 26: DDR\_HCAL Bit Definitions

	Physical Address 0x4810_0060								DDR_HCAL								Dynamic Memory Controller															
User Settings																																
Bit	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
	HCEN	reserved	reserved	HCPROG	SETALWAYS	r																										
Reset	0	?	0	0	1	0	0	0	?	?	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	?	0	0	0	0	0
	Bits		Access		Name		Description																									
	21:18		R/W		HCOFF3		Hardware Calibration Offset for DQS[3]: Provides a fractional offset from the value determined by the hardware calibration circuit. The offset range is 1/8 to 15/8 of a DDR data eye. The value programmed into delay line is $DQS[3] = (DDR\_DMCISR[ORV]) * HCOFF3$ . For a derivation of this formula, see Section 13.10.1.4. 0b0000 = 0 - No offset (strobe centered) 0b0001 to 0b0111 = 1/8 to 7/8 - Offset (moves strobe left of center) 0b1000 = 8/8 - No offset (strobe centered) 0b1001 to 0b1111 = 9/8 to 15/8 - Offset (moves strobe right of center)																									
	17:14		R/W		HCOFF2		Hardware Calibration Offset for DQS[2]: Provides a fractional offset from the value determined by the hardware calibration circuit. The offset range is 1/8 to 15/8 of a DDR data eye. The value programmed into delay line is $DQS[2] = (DDR\_DMCISR[ORV]) * HCOFF2$ . For a derivation of this formula, see Section 13.10.1.4. 0b0000 = 0 - No offset (strobe centered) 0b0001 to 0b0111 = 1/8 to 7/8 - Offset (moves strobe left of center) 0b1000 = 8/8 - No offset (strobe centered) 0b1001 to 0b1111 = 9/8 to 15/8 - Offset (moves strobe right of center)																									



## Specification Update PXA3xx (88AP3xx) Processor Family

---

---

### Disclaimer

No part of this document may be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying and recording, for any purpose, without the express written permission of Marvell. Marvell retains the right to make changes to this document at any time, without notice. Marvell makes no warranty of any kind, expressed or implied, with regard to any information contained in this document, including, but not limited to, the implied warranties of merchantability or fitness for any particular purpose. Further, Marvell does not warrant the accuracy or completeness of the information, text, graphics, or other items contained within this document.

Marvell products are not designed for use in life-support equipment or applications that would cause a life-threatening situation if any such products failed. Do not use Marvell products in these types of equipment or applications.

With respect to the products described herein, the user or recipient, in the absence of appropriate U.S. government authorization, agrees:

- 1) Not to re-export or release any such information consisting of technology, software or source code controlled for national security reasons by the U.S. Export Control Regulations ("EAR"), to a national of EAR Country Groups D:1 or E:2;
- 2) Not to export the direct product of such technology or such software, to EAR Country Groups D:1 or E:2, if such technology or software and direct products thereof are controlled for national security reasons by the EAR; and,
- 3) In the case of technology controlled for national security reasons under the EAR where the direct product of the technology is a complete plant or component of a plant, not to export to EAR Country Groups D:1 or E:2 the direct product of the plant or major component thereof, if such direct product is controlled for national security reasons by the EAR, or is subject to controls under the U.S. Munitions List ("USML").

At all times hereunder, the recipient of any such information agrees that they shall be deemed to have manually signed this document in connection with their receipt of any such information. Copyright © 2011. Marvell International Ltd. All rights reserved. Marvell, the Marvell logo, Moving Forward Faster, Alaska, Fastwriter, Datacom Systems on Silicon, Libertas, Link Street, NetGX, PHYAdvantage, Pretera, Raising The Technology Bar, The Technology Within, Virtual Cable Tester, and Yukon are registered trademarks of Marvell. Ants, AnyVoltage, Discovery, DSP Switcher, Feroceon, GalNet, GalTis, Horizon, Marvell Makes It All Possible, RADLAN, UniMAC, and VCT are trademarks of Marvell. All other trademarks are the property of their respective owners.

Marvell Semiconductor, Inc.  
5488 Marvell Lane  
Santa Clara, CA 95054, USA  
Tel: 1.408.222.2500  
Fax: 1.408.752.9028  
Email: [commsales@marvell.com](mailto:commsales@marvell.com)  
[www.marvell.com](http://www.marvell.com)