

Temporary Product Introduction Notification (TPIN): Apalis iMX6D 1GB IT V1.1Y 07-04-2022

Date of publication: 07 Apr 2022

Table of Contents

- 1. Affected Product Numbers
- 2. Product Phase in / Phase-out Schedule
- 3. Description of Changes
 - Change: Removed STMPE811QT
- 4. Customer Impact
 - Hardware
 - Software
 - Customer software
 - Toradex Linux BSP
 - Windows CE
- 5. Contact

1. Affected Product Numbers

Affected Products		Temporary Introduced Product	
		(with limited features)	
Part Number	Product Name	Part Number	Product Name
00351102	Apalis iMX6D 1GB IT V1.1C	00351124	Apalis iMX6D 1GB IT V1.1Y

2. Product Phase in / Phase-out Schedule

Affected Products		Temporary Introduced Product (with limited features)	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
00351102	Product will continue under allocation with limited availability due to component shortage.	00351124	Product available upon request

Customers not requiring the resistive touch controller and/or ADC are strongly encouraged to use the additional substitution version. Toradex also advises customers to validate the new product version before their production release, we can provide a rework instruction or "Sample" of the additional substitution version.

3. Description of Changes

Change: Removed STMPE811QT

 Removed STMPE811QTR touch controller and related components due to temporary component shortage



4. Customer Impact

Hardware

- 4-wire resistive touch functionality (Apalis pins 315, 317, 319, 321) won't be available in V1.1Y. No changes are required on the Apalis carrier board.
- Analog input functionality (Apalis pins 305, 307, 309, 311) won't be available in V1.1Y.
 No changes are required on the Apalis carrier board.

Software

Customer software

We request customers to check their own software in detail to guarantee functionality on the new product version. For example, please check that no excessive warning or error logging is done in the background which might compromise system performance or flash storage lifetime.

Toradex Linux BSP

- The removal of the components listed in the table should not affect the functionality of the software. A few error messages may appear on the console and in related log files.
 - Linux console demo: Apalis-iMX6 Console-Image 3.0b4.254 20200421

Linux LXDE: Apalis-iMX6_LXDE-Image 2.8b7. 20200610

Monthly release: 5.2.0-devel-202102+build.7

Linux multimedia image, Linux multimedia image with upstream, Linux minimal image, Linux minimal image with upstream

The boot sequence didn't register any problem for both modules (crashes, delays, getting stuck)

touchscreen controller errors:

```
stmpe-i2c 0-0041: failed to read regs 0x0: -6
```

Errors from Toradex Easy Installer: Apalis-iMX6_ToradexEasyInstaller_1.8-20181019

```
[ 0.140136] stmpe-i2c 2-0041: failed to read regs 0x0: -5
[ 0.823571] snvs-secvio 20cc000.caam-snvs: can't get snvs clock
[ 1.295186] rtc-ds1307 1-0068: hctosys: unable to read the hardware clock
```



- The functionality of 4-wire touch and analog inputs are not available in software, since the relevant HW components were removed. Besides the additional errors/warning output, there is no impact on software.
- Modifying the device tree to indicate the HW change will remove the error messages. A
 dedicated page with more information can be found here: https://developer.toradex.com
 /knowledge-base/software-adjustments-for-colibri-apalis-imx6-v11z-modules
- The boot sequence does not show any problems (crashes, delays, getting stuck)

Windows CE

 WinCE: No impact and no errors displayed. The WinCE BSP recognizes the absence of the ADC/Touch controller and unloads automatically.

5. Contact

- Please contact Toradex if you have any questions.
- For commercial and sales questions, please contact shop@toradex.com
- For technical questions, please contact support@toradex.com