



Verdin DSI to LVDS Adapter

Errata Document

Document Revision History

Date	Doc. Rev.	Notes
2020-03-06	Rev. 0.9	Initial Release
2020-04-10	Rev. 0.91	Removed HAR-3105 as it is fixed
14-Apr-2020	Rev. 0.92	Minor cosmetic improvements

Overview

Errata #1: HAR-2282 - Wrong capacitor polarity indicated on silkscreen4

HAR-2282 - Wrong capacitor polarity indicated on silkscreen

Affected Version: **Verdin DSI to LVDS Adapter V1.0**
Fixed in: **Next product version**

Customer Impact

Customers need to pay attention when measuring the voltage at capacitors to follow correct polarity.

Description

Capacitors C4, C5, C9 polarity indicator is not correct on the product silkscreen.

Workaround

Not required. The capacitors are assembled according to proper voltage polarity

DISCLAIMER:

Copyright © Toradex AG. All rights are reserved. The information and content in this document are provided “as-is” with no warranties of any kind and are for informational purposes only. Data and information have been carefully checked and are believed to be accurate; however, no liability or responsibility for any errors, omissions or inaccuracies is assumed.

Brand and product names are trademarks or registered trademarks of their respective owners. Specifications are subject to change without notice