


Clover

HW Errata



Revision History

Document Revisions

Date	Doc. Revision	Product Version	Changes
17-Jul-2025	Rev. 0.1	V1.0	Initial documentation Section 1 : added

Contents

1	Errata #1: HAR-12346 – The ETH_2_XGMII signals are swapped	3
1.1	Customer Impact	3
1.2	Description	3
1.3	Workaround	3

1 Errata #1: HAR-12346 – The ETH_2_XGMII signals are swapped

Affected version:

Clover V1.0

Fixed in:

Clover V1.1

1.1 Customer Impact

Ethernet Interface - ETH2 - does not work.

1.2 Description

The ETH_2_XGMII signal lines are swapped, resulting in the ETH2 interface being non-functional.

1.3 Workaround

None

DISCLAIMER

Copyright © Toradex AG. All rights are reserved. The information and content in this document are provided "as-is" with no warranties of any kind and are for informational purposes only. Data and information have been carefully checked and are believed to be accurate; however, no liability or responsibility for any errors, omissions or inaccuracies is assumed.

Brand and product names are trademarks or registered trademarks of their respective owners. Specifications are subject to change without notice.