Apalis T30 Mezzanine

Errata Document



Document Revision History

Date	Doc. Rev.	Notes
2018-05-08	Rev. 1.0	Errata #1: Added
2018-05-17	Rev. 1.1	Updated product image on the cover page

Overview

Errata #1: I2C signals (I2C3) shared between CSI connectors 4

Errata #1: I2C signals (I2C3) shared between CSI connectors

Affected Version: **Apalis T30 Mezzanine V2.0**

Fixed in: **No redesign scheduled**

1.1 Description

The Apalis T30 Mezzanine CSI connectors X3, X4 share same I2C signals (I2C3). It is therefore **not** possible to address multiple CSI cameras with the **same I2C slave address**.
For example: It is not possible to connect multiple Toradex CSI Camera Module 5MP OV5640 with Apalis T30 Mezzanine V2.0 at the same time.

1.2 Workaround

No workaround is possible.

DISCLAIMER:

Copyright© Toradex AG. All rights reserved. All data is for information purposes only and not guaranteed for legal purposes. Information has been carefully checked and is believed to be accurate; however, no responsibility is assumed for inaccuracies.

Brand and product names are trademarks or registered trademarks of their respective owners. Specifications are subject to change without notice.