# Product Change Notification - 0062 Colibri iMX6ULL 1GB IT V1.1A

Date of publication: 03 Sep 2024

## Table of Contents

## 1. Affected Products

| End of Life Product | | Replacement Product | |
|---|---|---|---|
| **Part Number** | **Product Name** | **Part Number** | **Product Name** |
| 00621100 | Colibri iMX6ULL 1GB IT V1.1A | 00621103 | Colibri iMX6ULL 1GB IT V1.1D |

## 2. Product Phase-in / Phase-out Schedule

| End of Life Product | | Replacement Product | |
|---|---|---|---|
| **Part Number** | **Estimated Schedule** | **Part Number** | **Estimated Schedule** |
| 00621100 | Last time buy (LTB): 2025-02-22<br><br>Last time ship (LTS): 2025-08-21 | 00621103 | Samples: Q4/2024 |

## 3. Description of Changes

### Change #1: RAM Change

The RAM part Micron MT41K512M16VRN-107 IT:P has been replaced with the Micron MT41K512M16VRP-107 IT:P.

# 4. Customer Impact

| **Hardware** |
| --- |
| No impact is expected, however please carefully verify the new product version in your environment. |

| **Software** |
| --- |
| **Torizon OS**<br><br>No impact is expected due to the RAM change.<br><br>**Toradex Embedded Linux BSP**<br><br>No impact is expected due to the RAM change. |

# 5. Contact

| |
| --- |
| Please contact Toradex if you have any questions.<br>For commercial and sales questions, please contact shop@toradex.com<br>For technical questions, please contact support@toradex.com |