

## Errata Notification ERR.2015.10.21.1

This document details the assembly errata known at the time of publication for the Colibri Evaluation Board V3.2A.

Date of Publication: 2015-10-21

### 1. Toradex Product Numbers Affected

---

Affected Product		New Product	
Part Number	Product Name	Part Number	Product Name
01013200	Colibri Evaluation Board V3.2A	01013200	Colibri Evaluation Board V3.2B

### 2. Description of Assembly Errata

---

A wrong part has been assembled on the audio connector X26.

Inserting the plug in the X26 connector jacks will have the following results:

Summary of Assembly Errata Issues	
Plug inserted in the top blue jack	The signals LINEIN_L and LINEIN_R get connected together.
Plug inserted in the middle green jack	The signals HEADPHONE_AC_L and HEADPHONE_AC_R get connected together.
Plug inserted in the bottom pink jack	No functional impact.

### 3. Customer Impact

---

Customers who need to use the Line In and Headphone interfaces in stereo mode, can contact the Toradex RMA department and get the board fixed or replaced.

### 4. Contact

---

Please contact Toradex if you have any questions.

For commercial and sales questions please contact [shop@toradex.com](mailto:shop@toradex.com)

For technical questions please contact [support@toradex.com](mailto:support@toradex.com)

For RMA requests please visit the page: <https://www.toradex.com/support/return-material-authorisation>