

Product Change Notification

Transition from

Colibri Evaluation Board V3.2A to Colibri Evaluation Board V3.2B

Date of Publication: 2016-06-03

1. Toradex Product Numbers Affected

EOL Product		Replacement Product	
Part Number	Product Name	Part Number	Product Name
01013200	Colibri Evaluation Board V3.2A	01013201	Colibri Evaluation Board V3.2B

2. Product Phase in / Phase out Schedule

This product is in "Evaluation Product" status, therefore we don't provide any last-time-buy options.

EOL Product		Replacement Product	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
01013200	Product will be sold until inventory is depleted.	01013201	Product will be available once the V3.2A products are sold out.

3. Description of Changes

From 01013200 Colibri Evaluation Board V3.2A to 01013201 Colibri Evaluation Board V3.2B

A wrong part has been assembled on the audio connector X26 in version V3.2A. This was corrected in V3.2B. See Errata ERR.2015.10.21.1 for details: <http://docs.toradex.com/102907-err-2015-10-21-1-colibri-evaluation-board-v3-2a.pdf>

The wrongly assembled connector X26 on V3.2A lead to the following situation when inserting an audio plug to X26:

Summary of Assembly Errata Impacts	
Plug inserted in the top blue jack	The signals LINEIN_L and LINEIN_R get connected together.
Plug inserted in the middle green jack	The signals HEADPHONE_AC_L and HEADPHONE_AC_R get connected together.
Plug inserted in the bottom pink jack	No functional impact.

4. Customer Impact

Headphone and Line-In work in stereo mode on V3.2B which is the correct function.

5. Contact

Please contact Toradex if you have any questions.

For commercial and sales questions please contact shop@toradex.com

For technical questions please visit <http://www.toradex.com/support>