

Product Change Notification (PCN): 0015 Colibri iMX6DL 512MB V1.1Z to 0015 Colibri iMX6DL 512MB V1.1Y - Update Nov. 28 2023

Date of publication: 02 Dec 2021

Updated on: 02 Feb 2022 Rev. 2 Changes: Updated "Customer Impact" to provide the details on the boot partition size of the new SkyHigh eMMC.

Updated on 28 Nov 2023 Changes: Updated "Customer Impact" to provide details on replacing the pre-installed software from Toradex Easy Installer 1.8 to Toradex Easy Installer 5.3.0.

Table of Contents

- [1. Affected Product Numbers](#)
- [2. Product Phase in / Phase-out Schedule](#)
- [3. Description of Changes](#)
 - [Change #1: eMMC](#)
 - [Change #2: Toradex Easy Installer](#)
- [4. Customer Impact](#)
 - [Hardware](#)
 - [Software](#)
- [5. Contact](#)

1. Affected Product Numbers

End of Life Product		Replacement Product	
Part Number	Product Name	Part Number	Product Name
00151125	Colibri iMX6DL 512MB V1.1Z (temporary version)	00151124	Colibri iMX6DL 512MB V1.1Y (temporary version)

2. Product Phase in / Phase-out Schedule

End of Life Product		Replacement Product	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
00151125	Due to memory component supply issues, we can't assure last time buy (LTB) and last time ship (LTS) options. The current product version will be sold until limited inventory is depleted.	00151124	Samples December 2021 Volumes in January 2022

Toradex advises its customers to carefully validate the new product version before their production release. Samples for evaluation purposes will be available upon request.

3. Description of Changes

Change #1: eMMC

Affected products	Change
00151125 Colibri iMX6DL 512MB V1.1Z	Replacing eMMC: Micron MTFC4GACAJCN-1M WT with SkyHigh S40FC004C1B1C00

Change #2: Toradex Easy Installer

Affected products	Change
00151125 Colibri iMX6DL 512MB V1.1Z	Replacing the pre-installed software from Toradex Easy Installer 1.8 to Toradex Easy Installer 5.3.0.

4. Customer Impact

Hardware

- No impact on the hardware side is expected. However, please carefully verify the new product version in your environment.

Software

- eMMC changes usually do not affect customer software, however, please validate your use case. The SkyHigh S40FC004C1B1C00 eMMC has a different boot partition size than Micron MTFC4GACAJCN-1M WT. Since our config block is always located in the last block of the primary boot partition, the absolute address of the config block changes. Customers not specifically writing the config block or using relative addressing are not affected by this change. It is recommended to review and test your software, especially if you have customized Toradex-provided software or used your own software to take advantage of eMMC-specific features. This change could furthermore also affect factory programming.
- **The pre-installed software on the Replacement Product changes from Toradex Easy Installer 1.8 to Toradex Easy Installer 5.3.0. Toradex Easy Installer is typically used for the factory programming of SoMs.**

As Toradex Easy Installer 5.3.0 is featuring a newer major version of the Linux Kernel, there is a potential impact on customers' factory programming procedure. Therefore, we strongly advise to validate this new version of Toradex Easy Installer as soon as possible, especially if the factory programming procedure is relying on the following scripts: prepare_script, wrapup_script, error-script.

Customers can instantly download, install and validate the new version of Toradex Easy Installer. More information is available here: [Loading Toradex Easy Installer | Toradex Developer Center](#)

5. Contact

- Please contact Toradex if you have any questions.
- For commercial and sales questions, please contact shop@toradex.com
- For technical questions, please contact support@toradex.com