

Change Notification (PCN): 01821100 SMARC Development Board V1.1A to 01821101 SMARC Development Board V1.1B

Date of publication: Jul 7, 2025

Table of Contents

- [1. Affected Products](#)
- [2. Product Phase-in / Phase-out Schedule](#)
- [3. Description of Changes](#)
 - [Change #1: DisplayPort fix](#)
- [4. Customer Impact](#)
 - [Hardware](#)
 - [Software](#)
- [5. Contact](#)

1. Affected Products

End of Life Product		Replacement Product	
Part Number	Product Name	Part Number	Product Name
01821100	SMARC Development Board V1.1A	01821101	SMARC Development Board V1.1B

2. Product Phase-in / Phase-out Schedule

End of Life Product		Replacement Product	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
01821100	Jul 7, 2025 EOL	01821101	Jul 9, 2025 Samples available

3. Description of Changes

Change #1: DisplayPort fix

- Change DisplayPort HPD Pull-up as workaround for SMARC iMX95 V1.0 Errata

4. Customer Impact

Hardware

- DisplayPort will work correctly with SMARC iMX95 V1.0

Software

- Embedded Linux BSP: DisplayPort will work correctly with SMARC iMX95 V1.0
- Toradex Easy Installer: N/A
- Torizon: DisplayPort will work correctly with SMARC iMX95 V1.0

5. Contact

- Please contact Toradex if you have any questions.
- For commercial and sales questions, please contact shop@toradex.com
- For technical questions, please contact support@toradex.com